Register entry, as of 28 October 2026 Listed for sale Record ID 989f69e5b7f7

# 2021 Nissan Rogue SV

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5N1 | AT3BB | 3 | M | C | 684411 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan North America, Inc. | Rogue · 2.5 L | Verified | 2021 | Smyrna | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.5 L, 4 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Rogue | Drive | 4WD |
| Trim | SV | Maker | NISSAN NORTH AMERICA, INC. |
| Body | Sport Utility Vehicle | Plant | Smyrna, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/rogue/2021

**9** recalls listed by Transport Canada for this model year

### Engine

2025356 27 Jun 2025

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with 1.5 L or 2.0 L variable compression engines. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. On certain vehicles, the dealer will also update the engine control module.

### Visual system

2022599 21 Oct 2022

Issue: Under certain conditions, a software problem could cause the in-vehicle infotainment system to continuously reboot. If this happens, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and ask you to make an appointment with your local dealer to update the in-vehicle infotainment system software. For vehicles with over-the-air (OTA) update capability, Nissan will send a wireless over-the-air software update to each vehicle.

### Seats and restraints

2022498 2 Sep 2022

Issue: On certain vehicles, the left- and right-rear seat belts may not retract to their storage position. Canadian regulations require seat belts to retract fully when not in use. Safety Risk: A seat belt that doesn't retract properly could be difficult to use. Not wearing a seat belt can increase the risk of injury in a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the left- and right-rear seat belts. They will be replaced, if necessary.

### Visual system

2022398 22 Jul 2022

Issue: Under certain conditions, a software problem could cause the in-vehicle infotainment system to reset. If you shift to reverse while the computer is resetting, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: This recall only affects certain vehicles sold to rental fleets. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and ask you to make an appointment with your local dealer to update the in-vehicle infotainment system software. For vehicles with over-the-air (OTA) update capability, Nissan will send a wireless over-the-air software update to each vehicle.

### Lights and instruments

2022153 29 Mar 2022

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it gets dark. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it gets dark could reduce visibility and increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to reprogram the body control module (BCM).

### Fuel system

2021754 10 Dec 2021

Issue: On certain vehicles, the fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power while driving could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

3 more on the model-year record, cardog.app/tools/recalls/nissan/rogue/2021

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $24,827[5], $3,833 over the median of $20,994[4].

| | |
|---|---|
| Lowest ask | $12,999 |
| Middle half | $18,994 – $22,995 |
| Median ask | $20,994 |
| This car | $24,827 |

Same configuration · 82 live listings · as of 28 Oct 2026

### OTHER 2021 NISSAN ROGUE LISTINGS [5]

| | |
|---|---|
| Kingston, ON · 62,685 km | $25,491 |
| Calgary, AB · 47,803 km | $28,851 |
| Ottawa, ON · 89,224 km | $22,495 |
| Edmonton, AB · 125,154 km | $23,980 |
| Westville, NS · 104,300 km | $19,995 |
| Sherwood Park, AB · 125,154 km | $23,980 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Smyrna, Tennessee, United States |
| 12 Feb 2021 | Transport Canada recall 2021062[2]<br>Issued for the model year · Fuel system |
| 26 Apr 2021 | Transport Canada recall 2021245[2]<br>Issued for the model year · Brakes |
| 28 Jun 2021 | Transport Canada recall 2021397[2]<br>Issued for the model year · Seats and restraints |
| 10 Dec 2021 | Transport Canada recall 2021754[2]<br>Issued for the model year · Fuel system |
| 29 Mar 2022 | Transport Canada recall 2022153[2]<br>Issued for the model year · Lights and instruments |
| 22 Jul 2022 | Transport Canada recall 2022398[2]<br>Issued for the model year · Visual system |
| 2 Sep 2022 | Transport Canada recall 2022498[2]<br>Issued for the model year · Seats and restraints |
| 21 Oct 2022 | Transport Canada recall 2022599[2]<br>Issued for the model year · Visual system |
| 27 Jun 2025 | Transport Canada recall 2025356[2]<br>Issued for the model year · Engine |
| 26 Oct 2026 | Listed for sale, Innisfail, AB[5]<br>Innisfail Chrysler Dodge Jeep Ram · asking $24,827 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $24,827 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 82 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.