Register entry, as of 11 November 2026 Listed for sale Record ID 4b08ef2ee47c

2007 Hyundai Santa Fe CMA

3.3 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NM	SH73E	X	7	H	082900
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Manufactur…	Santa Fe · 3.3 L	Verified	2007	Alabama	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.3 L, 6 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Santa Fe	Drive	AWD
Trim	CMA	Maker	HYUNDAI MOTOR MANUFACTURING ALABAMA LLC (HMMA)
Body	Sport Utility Vehicle	Plant	Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2007

9 recalls listed by Transport Canada for this model year

Engine

2021653 26 Oct 2021

Issue: On certain vehicles, engine oil can leak from the valve cover onto the alternator. If this happens, the charging system could stop working and cause a warning light to turn on. If you continue to drive the vehicle with this problem, the engine could shut off while driving, and you may not be able to restart it. Note: This recall replaces C0260 (Transport Canada recall 2016-309). Vehicles that were repaired under that recall also require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail. The corrective actions for this recall are under development. Note: If the battery charging indicator light is on, Hyundai recommends that you should arrange to have the vehicle inspected and repaired at a dealer immediately.

Electrical

2020233 27 May 2020

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause overheating of the control module. Note: This recall only affects Hyundai Genuine Accessory trailer wiring harness kits that were manufactured by third parties and sold in Canada. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk. This risk remains even when the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to inspect your vehicle to see if it has an affected trailer wiring harness installed. If it does, Hyundai will advise you to take your vehicle to a dealer to install a redesigned trailer wiring harness. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Engine
2016309 16 Jun 2016

This recall was replaced by Transport Canada Recall No. 2021-653. On certain vehicles equipped with a 3.3L V6 engine, engine oil can leak onto the alternator, which could affect charging system function and potentially cause the engine to stall and not restart. This would result in a loss of motive power as well as affect power braking and power steering system function, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the front valve cover gasket and repair/replace the alternator, as necessary, under a special service campaign.

Electrical
2013099 3 Apr 2013

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

Airbag
2012231 24 Jul 2012

On certain vehicles equipped with an advanced airbag system, the Passive Occupant Detection System (PODS), installed in the right front seat of the vehicle, may misclassify a small stature adult as a child and deactivate the passenger frontal airbag. When the passenger frontal airbag is deactivated, the “PASS AIR BAG OFF” warning lamp will illuminate. This would cause the right front airbag to not inflate in a crash that merits airbag deployment, and may result in injury to the right front seat occupant. The condition will not affect the driver’s frontal airbag deployment. Correction: Dealers will reprogram the PODS system.

Airbag
2011333 9 Sep 2011

On certain vehicles, the clockspring assembly for the driver's airbag may become damaged and fail. As a result the airbag may not function as intended, and the instrument panel warning lamp would illuminate. Failure of the driver's frontal airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect and, if necessary, replace the airbag clockspring assembly.

3 more on the model-year record, cardog.app/tools/recalls/hyundai/santa-fe/2007

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply. Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $1,000[5], $988 under the median of $1,988[4].



Lowest ask	$1,000
Middle half	$1,494 – $4,934
Median ask	$1,988
This car	$1,000

Same model year · 3 live listings · as of 11 Nov 2026

OTHER 2007 HYUNDAI SANTA FE LISTINGS [5]

Grand Forks, BC · 196,832 km	$7,880
Mississauga, ON · 297,546 km	$1,988

§4 EVENTS

2007	Model year 2007[1] Assembly plant Alabama, United States
29 Aug 2006	Transport Canada recall 2006205[2] Issued for the model year · Fuel system
10 Jun 2008	Transport Canada recall 2008206[2] Issued for the model year · Label
23 Apr 2009	Transport Canada recall 2009120[2] Issued for the model year · Lights and instruments
9 Sep 2011	Transport Canada recall 2011333[2] Issued for the model year · Airbag
24 Jul 2012	Transport Canada recall 2012231[2] Issued for the model year · Airbag
3 Apr 2013	Transport Canada recall 2013099[2] Issued for the model year · Electrical
16 Jun 2016	Transport Canada recall 2016309[2] Issued for the model year · Engine
27 May 2020	Transport Canada recall 2020233[2] Issued for the model year · Electrical
26 Oct 2021	Transport Canada recall 2021653[2] Issued for the model year · Engine
9 Nov 2026	Listed for sale, Dartmouth, NS[5] Fairley &a; Stevens Ford · asking $1,000
11 Nov 2026	Listing last updated[5] asking $1,000

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 3 live listings, as of 11 Nov 2026

[5] Live public dealer listings on Cardog, as of 11 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.