Register entry, as of 29 October 2026 Listed for sale Record ID 9505787418df

2015 Hyundai Elantra GLS(Middle)

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NP	DH4AE	9	F	H	562485
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai-Kia America Tech…	Elantra · 1.8 L	Verified	2015	Alabama	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra	Drive	Not in the decode
Trim	GLS(Middle)	Maker	HYUNDAI-KIA AMERICA TECHNICAL CENTER INC (HATCI)
Body	Sedan	Plant	Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2015

9 recalls listed by Transport Canada for this model year

Airbag

2026234 14 May 2026

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not fully inflate and fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver-front airbag inflator.

Structure

2024126 23 Feb 2024

Issue: On certain vehicles, a part in the trunk release latch could fail. If this happens, the emergency trunk release located inside the trunk may not work properly. This could prevent a person that is trapped inside the trunk from opening it. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the trunk latch assembly.

Brakes

2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

3 more on the model-year record, cardog.app/tools/recalls/hyundai/elantra/2015

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,990[5], $805 under the median of $7,795[4].



Lowest ask	$5,871
Middle half	$7,066 – $8,374
Median ask	$7,795
This car	$6,990

Same configuration · 14 live listings · as of 29 Oct 2026

OTHER 2015 HYUNDAI ELANTRA LISTINGS [5]

Val-Bélair, QC · 115,740 km	$9,555
Nanaimo, BC · 155,928 km	$9,695
Mirabel, QC · 140,707 km	$8,577
Terrebonne, QC · 140,707 km	$8,577
Sault Ste. Marie, ON · 88,733 km	$10,995
Ottawa, ON · 158,818 km	$7,498

§4 EVENTS

2015	Model year 2015[1] Assembly plant Alabama, United States
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
27 Jan 2021	Transport Canada recall 2021034[2] Issued for the model year · Engine
17 Sep 2021	Transport Canada recall 2021575[2] Issued for the model year · Engine
8 May 2022	Transport Canada recall 2022244[2] Issued for the model year · Engine
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
22 Sep 2023	Transport Canada recall 2023527[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
23 Feb 2024	Transport Canada recall 2024126[2] Issued for the model year · Structure
14 May 2026	Transport Canada recall 2026234[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC[5] Prilo Occasion · asking $6,990
29 Oct 2026	Listing last updated[5] asking $6,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 14 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.