Register entry, as of 28 October 2026 Listed for sale Record ID 14d1565c3757

2020 Toyota Highlander XLE

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD	GZRBH	2	L	S	511044
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Highlander · 3.5 L	Verified	2020	Princeton	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Highlander	Drive	4WD
Trim	XLE	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Sport Utility Vehicle	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/highlander/2020

5 recalls listed by Transport Canada for this model year

Airbag

2023684 20 Dec 2023

Issue: On certain vehicles, a sensor for the occupant classification system (OCS) may not have been manufactured properly. As a result, the sensor could short circuit and cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a warning message to display on the instrument panel and the airbag indicator light would display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the OCS sensor.

Structure

2023574 26 Oct 2023

Issue: On certain vehicles, the front lower bumper cover may not be attached properly. As a result, if there is a minor impact to the front bumper, the lower bumper cover, engine under cover, and the fender liners could separate from the vehicle while driving. Safety Risk: Parts that detach from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Action: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front bumper cover and secure it. If damage is found, the dealer will also replace the upper and/or lower front bumper cover(s).

Brakes

2022179 13 Apr 2022

Issue: Under certain conditions, the vehicle stability control (VSC) system may not switch on when the ignition is restarted. This can happen if the driver manually turns off the VSC, depresses the brake pedal, and then turns off and restarts the vehicle while continuously depressing the brake pedal. Canadian regulations require the stability control system to be active each time that you start the vehicle. Safety Risk: A stability control system that is switched off could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to update the skid control ECU software.

Airbag

2020480 14 Oct 2020

Issue: On certain vehicles, one or both of the front seats may have an incorrect trim cover installed. This could prevent the front seat-mounted side airbags from inflating properly in a crash. Safety Risk: An airbag that does not work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front seat trim covers. They will be replaced, as necessary.

Powertrain

2020111 19 Mar 2020

Issue: On certain vehicles, the engine stop-start system may not work properly and could cause the engine to stall while driving. If this happens, a warning chime will sound and multiple warning lights would turn on to let the driver know that the engine has stopped. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to update the engine control unit (ECU) software.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,888[5], the median[4].

Lowest ask	$29,991
Middle half	$33,116 – $36,874
Median ask	$34,888
This car	$34,888

Same configuration · 19 live listings · as of 28 Oct 2026

OTHER 2020 TOYOTA HIGHLANDER LISTINGS [5]

Brantford, ON · 69,000 km	$33,113
Vaudreuil-Dorion, QC · 130,848 km	$29,991
Gatineau, QC · 73,227 km	$34,985
Vanier, QC · 113,808 km	$28,980
Newmarket, ON · 104,691 km	$32,488
Newmarket, ON · 122,963 km	$32,990

§4 EVENTS

2020	Model year 2020[1] Assembly plant Princeton, Indiana, United States
19 Mar 2020	Transport Canada recall 2020111[2] Issued for the model year · Powertrain
14 Oct 2020	Transport Canada recall 2020480[2] Issued for the model year · Airbag

13 Apr 2022	Transport Canada recall 2022179[2] Issued for the model year · Brakes
26 Oct 2023	Transport Canada recall 2023574[2] Issued for the model year · Structure
20 Dec 2023	Transport Canada recall 2023684[2] Issued for the model year · Airbag
19 Oct 2026	Listed for sale, Brampton, ON[5] Performance Hyundai Brampton · asking $34,888
28 Oct 2026	Listing last updated[5] asking $34,888

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 19 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.