Register entry, as of 29 November 2026 Listed for sale Record ID 37c5c1c45acd

2005 Toyota Sienna LE

3.3 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD	ZA23C	6	5	S	235996
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Sienna · 3.3 L	Verified	2005	Princeton	Build sequence

§1 IDENTITY [1]

Model year	2005	Engine	3.3 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Sienna	Drive	4x2
Trim	LE	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Minivan	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/sienna/2005

7 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Powertrain

2017505 18 Oct 2017

On certain vehicles, the transmission may be shifted out of PARK without first depressing the brake pedal. This could result in unintended vehicle movement, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the shift lock solenoid.

Structure

2014188 22 May 2014

On certain vehicles operated where road salts are frequently used, corrosion of the spare tire carrier assembly cable may cause the separation of the spare tire stowed under the vehicle. The spare tire falling on the road surface creates a safety hazard that may result in a crash causing injury and/or property damage. Correction: As an interim measure, dealers will remove the spare tire and store it in the cargo area of the vehicle. Dealers will replace the spare tire carrier assembly when parts become available. Note: This recall supersedes recall 2010-123. Vehicles that were inspected and/or repaired under the previous recall may still be at risk of spare tire separation and will require re-inspection and/or repair.

Powertrain

2013329 26 Sep 2013

On certain vehicles, the transmission may be shifted out of PARK without first depressing the brake pedal. This could result in inadvertent vehicle movement, which could cause a crash resulting in injury and/or property damage. Correction: Dealers will replace the shift lock solenoid.

Steering

2011397 9 Nov 2011

On certain vehicles equipped with a 1MZ-FE or 3MZ-FE V6 engine, the crankshaft pulley may fail. The outer ring may become misaligned, or it may not properly rotate, causing noise and/or illumination of the discharge warning light. In addition, the power steering belt may become detached from the crankshaft pulley, which could result in a sudden increase in steering effort. A loss of steering power assist could result in a crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the crankshaft pulley.

Other

2010123 19 Apr 2010

On certain vehicles operated where road salts are frequently used, excessive corrosion of the spare tire carrier assembly cable may cause the separation of the spare tire stowed under the vehicle. Spare tire falling on the road surface creates a safety hazard that may result in a crash causing property damage, personal injury or death. Correction: Dealers will inspect and, as required, either apply a corrosion resistance enhancement treatment to the spare tire carrier restraint cable, repair the cable and apply the corrosion resistance treatment, or replace the spare tire carrier assembly. Note: This recall has been superseded by recall 2014-188.

1 more on the model-year record, cardog.app/tools/recalls/toyota/sienna/2005

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,298[5], the median[4].



Lowest ask	$4,999
Middle half	$5,148 – $5,749
Median ask	$5,298
This car	$5,298

Same model year · 3 live listings · as of 29 Nov 2026

OTHER 2005 TOYOTA SIENNA LISTINGS [5]

Richmond, BC · 296,916 km	$4,999
Surrey, BC · 267,281 km	$6,200

§4 EVENTS

2005	Model year 2005[1] Assembly plant Princeton, Indiana, United States
20 Jun 2005	Transport Canada recall 2005223[2] Issued for the model year · Seats and restraints
19 Apr 2010	Transport Canada recall 2010123[2] Issued for the model year · Other
9 Nov 2011	Transport Canada recall 2011397[2] Issued for the model year · Steering
26 Sep 2013	Transport Canada recall 2013329[2] Issued for the model year · Powertrain
22 May 2014	Transport Canada recall 2014188[2] Issued for the model year · Structure
18 Oct 2017	Transport Canada recall 2017505[2] Issued for the model year · Powertrain
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
13 Nov 2026	Listed for sale, Vaughan, ON[5] Maple Toyota · asking $5,298
28 Nov 2026	Listing last updated[5] asking $5,298

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 3 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.