Register entry, as of 28 October 2026 Listed for sale Record ID f372e87fcc8a

2018 Toyota Tundra SR5

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF	DY5F1	X	J	X	757584
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tundra · 5.7 L	Verified	2018	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	5.7 L, 8 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tundra	Drive	4WD
Trim	SR5	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2018

9 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Steering

2021718 23 Nov 2021

Issue: On certain vehicles, a defect in the steering gear assembly could cause it to leak power steering fluid. If this happens, there could be a loss of power steering assist. Note: For 2007-2020 models, this recall only affects 41 vehicles that had a replacement steering gear installed in 2021. Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low speeds. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace power steering gear assembly.

Lights and instruments

2021544 2 Sep 2021

Issue: On certain trucks equipped with halogen headlamps, when the high beams are switched on, both the high and low beam lights turn on. Under certain conditions, this could cause the headlamps and wiring to overheat. Safety Risk: A headlamp that overheats can cause a loss of lighting and could create a fire risk. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to modify the engine wire harness assembly. The dealer will also inspect the headlamp assemblies, bulbs and bulb connectors for damage. The dealer will replace parts damaged by this problem.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Lights and instruments

2020321 15 Jul 2020

Issue: On certain vehicles, the wire harness for the front turn signal lights was assembled incorrectly. As a result, the turn signals and hazard warning lights are not bright enough to meet Canadian regulations. This could cause other road users not to notice when the signal or hazard warning lights are turned on. Safety Risk: Signal lights that are not bright enough could make the vehicle less visible to others, and could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to modify the wire harness for the front turn signal lights.

Fuel system

2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

3 more on the model-year record, cardog.app/tools/recalls/toyota/tundra/2018

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $42,995[5], $8,996 over the median of $33,999[4].



Lowest ask	$21,888
Middle half	$30,497 – $42,869
Median ask	$33,999
This car	$42,995

Same model year · 22 live listings · as of 28 Oct 2026

OTHER 2018 TOYOTA TUNDRA LISTINGS [5]

Kentville, NS · 183,138 km	$32,777
Smiths Falls, ON · 110,000 km	$52,930
Laval, QC · 111,961 km	$43,995
Penticton, BC · 229,980 km	$31,995

Yarmouth, NS · 183,138 km	$32,777
Middleton, NS · 183,138 km	$32,777

§4 EVENTS

2018	Model year 2018[1] Assembly plant San Antonio, Texas, United States
21 Feb 2018	Transport Canada recall 2018100[2] Issued for the model year · Electrical
5 Oct 2018	Transport Canada recall 2018547[2] Issued for the model year · Airbag
13 Jan 2020	Transport Canada recall 2020005[2] Issued for the model year · Fuel system
4 Mar 2020	Transport Canada recall 2020088[2] Issued for the model year · Fuel system
15 Jul 2020	Transport Canada recall 2020321[2] Issued for the model year · Lights and instruments
28 Oct 2020	Transport Canada recall 2020514[2] Issued for the model year · Fuel system
2 Sep 2021	Transport Canada recall 2021544[2] Issued for the model year · Lights and instruments
23 Nov 2021	Transport Canada recall 2021718[2] Issued for the model year · Steering
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
25 Oct 2026	Listed for sale, Edmonton, AB[5] Lexus South Pointe · asking $42,995
26 Oct 2026	Listing last updated[5] asking $42,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 22 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.