Register entry, as of 29 October 2026 Listed for sale Record ID d286f0e3c6a0

# 2022 Toyota Tundra Limited

3.4 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5TF | JA5DA | 2 | N | X | 021674 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Tundra · 3.4 L | Verified | 2022 | Texas | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 3.4 L, 6 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Tundra | Drive | 4WD |
| Trim | Limited | Maker | TOYOTA MOTOR MANUFACTURING, TEXAS, INC. |
| Body | Pickup | Plant | Texas, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2022

**11** recalls listed by Transport Canada for this model year

### Visual system

2025522 1 Oct 2025

Issue: Under certain conditions, a problem with the rearview camera could cause the rearview camera image not to display correctly or at all. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects vehicles equipped with a 14-inch multimedia display. For the Tundra model, this recall affects both Tundra and Tundra hybrid models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners in writing and advise you to take your vehicle to a dealership to update the multimedia display software.

### Lights and instruments

2025263 15 May 2025

Issue: On certain trucks, the reverse lamp assemblies may not be sealed correctly. As a result, over time, water could leak into the lamp(s) and cause them not to work. Note: This recall affects both Tundra and Tundra Hybrid models. Safety Risk: Reverse lamps that don't work could cause others not to recognize when a vehicle is backing up, and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace both reverse lamp assemblies. Additionally, the dealer will inspect and, if necessary, repair the wiring for the reverse lamps.

### Engine

2024304 30 May 2024

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

### Powertrain

2024109 21 Feb 2024

Issue: On certain vehicles, a problem with the transmission could cause the vehicle to move forward when the driver shifts to the "N"(Neutral) position and the brakes or parking brake aren't applied. Note: For the Tundra model, this recall affects both Tundra and Tundra Hybrid models. For the Sequoia model, only the Sequoia Hybrid model is affected by this recall. Safety Risk: A vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software.

### Fuel system

2023445 10 Aug 2023

Issue: On certain trucks, a plastic fuel tube on the top of the fuel tank may not be secured correctly. As a result, the fuel tube could be damaged by contact with the brake lines and create a fuel leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership for an interim repair. Once replacement parts are available, you will need to return to the dealership to replace the fuel tube with an improved part and have additional clamps installed.

### Accessories

2023112 3 Mar 2023

Issue: On certain trucks, the bed-cover could come loose while driving and detach from the truck. Note: This recall affects Tundra and Tundra Hybrid models equipped with an optional Toyota genuine accessory tri-fold hard tonneau cover that was installed before delivery or sold as a dealer accessory. Safety Risk: A tonneau cover that separates from a moving vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Toyota will notify owners by mail and advise you to remove the tonneau cover. The corrective actions for this recall are under development. Toyota will send you a second notice when a final repair is available.

5 more on the model-year record, cardog.app/tools/recalls/toyota/tundra/2022

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $44,980[5], $2,997 under the median of $47,977[4].




| | |
|---|---|
| Lowest ask | $34,995 |
| Middle half | $43,996 – $54,472 |
| Median ask | $47,977 |
| This car | $44,980 |

Same model year · 63 live listings · as of 29 Oct 2026

### OTHER 2022 TOYOTA TUNDRA LISTINGS [5]

| | |
|---|---|
| Kelowna, BC · 81,997 km | $47,900 |
| Montmagny, QC · 42,075 km | $43,493 |
| Ottawa, ON · 66,219 km | $45,592 |
| Terrebonne, QC · 34,050 km | $44,999 |
| Cambridge, ON · 176,349 km | $43,988 |
| Courtenay, BC · 58,944 km | $46,999 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Texas, United States |
| 28 Apr 2022 | Transport Canada recall 2022215[2]<br>Issued for the model year · Visual system |
| 23 Jun 2022 | Transport Canada recall 2022330[2]<br>Issued for the model year · Powertrain |
| 13 Jul 2022 | Transport Canada recall 2022374[2]<br>Issued for the model year · Visual system |
| 1 Sep 2022 | Transport Canada recall 2022493[2]<br>Issued for the model year · Brakes |
| 22 Feb 2023 | Transport Canada recall 2023084[2]<br>Issued for the model year · Visual system |
| 3 Mar 2023 | Transport Canada recall 2023112[2]<br>Issued for the model year · Accessories |
| 10 Aug 2023 | Transport Canada recall 2023445[2]<br>Issued for the model year · Fuel system |
| 21 Feb 2024 | Transport Canada recall 2024109[2]<br>Issued for the model year · Powertrain |
| 30 May 2024 | Transport Canada recall 2024304[2]<br>Issued for the model year · Engine |
| 15 May 2025 | Transport Canada recall 2025263[2]<br>Issued for the model year · Lights and instruments |
| 1 Oct 2025 | Transport Canada recall 2025522[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Lloydminster, AB[5]<br>Boundary Ford Sales · asking $44,980 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $44,980 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 63 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.