Register entry, as of 27 October 2026 Listed for sale Record ID c5c373d023b6

2017 Toyota Tundra TRD Pro

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF	UY5F1	8	H	X	605622
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tundra · 5.7 L	Verified	2017	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	5.7 L, 8 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tundra	Drive	4WD
Trim	TRD Pro	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2017

5 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Steering

2021718 23 Nov 2021

Issue: On certain vehicles, a defect in the steering gear assembly could cause it to leak power steering fluid. If this happens, there could be a loss of power steering assist. Note: For 2007-2020 models, this recall only affects 41 vehicles that had a replacement steering gear installed in 2021. Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low speeds. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace power steering gear assembly.

Seats and restraints

2018097 20 Feb 2018

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard CMVSS 207 - Anchorage of Seats, CMVSS 210 - Seat Belt Anchorages, CMVSS 210.1 - User-ready Tether Anchorages for Restraint Systems and Booster Seats, and CMVSS 210.2 - Lower Universal Anchorage Systems for Restraint Systems and Booster Seats. One or more of the bolts fixing the left hand rear split seat bracket sub-assemblies to the floor pan may not have been tightened properly during assembly. This could allow the seat to move in the event of a crash, increasing the risk of injury to the seat occupant. Correction: Dealers will retighten the five seat leg bracket bolts.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Structure

2017036 24 Jan 2017

On certain vehicles equipped with the plastic rear step bumper, the resin reinforcement brackets that secure the step corners of the bumper could become damaged after a rear impact. If a person were to use the rear bumper steps with damaged resin reinforcement brackets, part of the bumper could break off which could cause the person to fall, increasing the risk of injury. Correction: Dealers will replace the resin reinforcement brackets with steel reinforcement brackets. In addition, the rear bumper tread covers will also be replaced.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $30,888[5], $7,906 under the median of $38,794[4].

Lowest ask	$26,900
Middle half	$33,452 – $42,246
Median ask	$38,794
This car	$30,888

Same model year · 16 live listings · as of 27 Oct 2026

OTHER 2017 TOYOTA TUNDRA LISTINGS [5]

Kingston, ON · 44,621 km	$41,995
New Westminster, BC · 120,166 km	$39,998
New Westminster, BC · 154,789 km	$42,998
Brampton, ON · 174,923 km	$37,994
Victoria, BC · 115,542 km	$40,595
Sainte-Marie, QC · 147,712 km	$32,999

§4 EVENTS

2017	Model year 2017[1] Assembly plant San Antonio, Texas, United States
24 Jan 2017	Transport Canada recall 2017036[2] Issued for the model year · Structure
20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical
20 Feb 2018	Transport Canada recall 2018097[2] Issued for the model year · Seats and restraints
23 Nov 2021	Transport Canada recall 2021718[2] Issued for the model year · Steering
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Milton, ON[5] Parkway Auto Trade · asking $30,888
27 Oct 2026	Listing last updated[5] asking $30,888

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 16 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.