Register entry, as of 29 October 2026 Listed for sale Record ID 3ba1c38f4648

2011 Kia Sorento GL

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	KTDA2	6	B	G	159531
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Sorento · 3.5 L	Verified	2011	Georgia	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.5 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Sorento	Drive	4WD
Trim	GL	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2011

10 recalls listed by Transport Canada for this model year

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Engine

2023695 22 Dec 2023

Issue: On certain vehicles, the engine could fail. An engine failure could cause a loss of power to the wheels and/or an engine fire. Note: This recall only affects vehicles equipped with a 2.4 L MPI engine. Vehicles repaired under Kia service campaign SC037 (Transport Canada recall no. 2021-040) already have the updated software, and don't require this repair. Safety Risk: A sudden loss power to the wheels could increase the risk of a crash. An engine fire can create a risk of injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. The dealer will also update the engine control module software. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Brakes

2023529 26 Sep 2023

Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse(s) for the HECU. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2021040 1 Feb 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.4 L MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Structure

2016120 17 Mar 2016

On certain vehicles, the sunroof can break due to external impacts, which can cause the sunroof crosspieces with some tempered glass attached to dislodge and drop into the passenger cabin onto occupants. Such breakage would be most prevalent in provinces where gravel road treatments for ice/snow and severe temperature shifts are common. Correction: Dealers will install additional connective pieces to prevent the possibility of sunroof crosspieces dropping under a product enhancement campaign. In the interim, owners are advised to drive with the sunshade in the closed position until the campaign is completed.

Powertrain

2015468 14 Oct 2015

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 102 - Transmission Control Functions. The transmission shift selector assembly could become damaged and allow the driver to shift the transmission out of the PARK gear position without depressing the brake pedal, contrary to the requirements of the standard. These issues could cause unintended vehicle movement, increasing the risk of injury and/or property damage. Correction: Dealers will replace the shift interlock assembly.

4 more on the model-year record, cardog.app/tools/recalls/kia/sorento/2011

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,980[5], $3,481 over the median of $4,499[4].

Lowest ask	$2,990
Middle half	$4,495 – $7,777
Median ask	$4,499
This car	$7,980

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2011 KIA SORENTO LISTINGS [5]

Nanaimo, BC · 272,356 km	$4,499
Mirabel, QC · 159,782 km	$7,777
Terrebonne, QC · 159,782 km	$7,777
Kelowna, BC · 272,356 km	$4,499
100 Mile House, BC · 272,356 km	$4,499
Québec, QC · 206,500 km	$4,495

§4 EVENTS

2011	Model year 2011[1] Assembly plant Georgia, United States
2 Sep 2010	Transport Canada recall 2010291[2] Issued for the model year · Electrical
24 Nov 2010	Transport Canada recall 2010425[2] Issued for the model year · Brakes
27 Apr 2011	Transport Canada recall 2011174[2] Issued for the model year · Powertrain
3 Apr 2013	Transport Canada recall 2013098[2] Issued for the model year · Brakes
14 Oct 2015	Transport Canada recall 2015468[2] Issued for the model year · Powertrain
17 Mar 2016	Transport Canada recall 2016120[2] Issued for the model year · Structure
1 Feb 2021	Transport Canada recall 2021040[2] Issued for the model year · Engine
26 Sep 2023	Transport Canada recall 2023529[2] Issued for the model year · Brakes
22 Dec 2023	Transport Canada recall 2023695[2] Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
22 Aug 2026	Listed for sale, Port Alberni, BC[5] Nexcar · asking $7,980
28 Oct 2026	Listing last updated[5] asking $7,980

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.