Register entry, as of 26 October 2026 Listed for sale Record ID a14fe5ced85f

# 2016 Tesla Model X

Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| 5YJ | XCAE2 | 8 | G | F | 019459 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Tesla, Inc. | Model X | Verified | 2016 | Fremont | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | Not in the decode |
| Make | Tesla | Fuel | Electric |
| Model | Model X | Drive | Not in the decode |
| Trim | Not in the decode | Maker | TESLA, INC. |
| Body | Sport Utility Vehicle | Plant | Fremont, California, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/tesla/model-x/2016

**10** recalls listed by Transport Canada for this model year

### Structure

2024483 16 Aug 2024

Issue: On certain vehicles, the inspection or repairs completed by a Tesla service center during recall SB-20-12-005 (Transport Canada recall no. 2020-553) may not have been effective. As a result, a second inspection and/or repair is required. On certain vehicles, two of the cosmetic roof trims may not be properly attached. This includes the cosmetic roof trim just behind the top of the windshield and the spine cosmetic roof trim between the rear doors. Over time, these cosmetic roof trims could loosen and separate from the vehicle. Note: This recall replaces Transport Canada recall no. 2020-553. Safety Risk: Cosmetic roof trims that detach from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Tesla will notify owners by email and advise you to contact Tesla Service to arrange for an inspection and, if necessary, repair or replace the cosmetic roof trims.

### Lights and instruments

2024283 21 May 2024

Issue: A previous over-the-air (OTA) software update could cause the vehicle not to display the correct visual warning indicators when there are problems with the brake system or when the parking brake is applied. As a result, the BRAKE, PARK, and antilock brake system (ABS) visual indicators would display as text instead of symbols. Safety Risk: While there is a low risk to safety, Canadian regulations require visual warnings to use common symbols, instead of words, to avoid driver confusion. Corrective Actions: Tesla will notify affected owners by email. Tesla has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2024.3.25, 2024.14.5, or a release later than 2024.14.5.

### Accessories

2023657 12 Dec 2023

Issue: On vehicles equipped with the Autosteer advanced driver-assistance feature, when using the feature, the vehicle may not provide strong enough warnings or monitor the driver closely enough to prevent misuse of the feature. Safety Risk: A driver that doesn't pay close attention while using the Autosteer feature or who doesn't react quickly when Autosteer is canceled could have an increased risk of a crash. Corrective Actions: Tesla will notify owners by email and supply an over-the-air software update to improve driver monitoring and alerts while using the Autosteer feature. Tesla advises that you must always pay attention and be ready to take control of the vehicle at any time while using the Autosteer advanced driver-assistance feature.

### Accessories

2023063 14 Feb 2023

Issue: In certain traffic situations, when the FSD Beta advanced driver assistance feature is engaged, the vehicle may perform maneuvers that break certain traffic laws, if the driver doesn't intervene and take control. Note: This recall only affects vehicles equipped with the FSD Beta feature. Safety Risk: Certain maneuvers performed by the FSD Beta advanced driver assistance feature may break traffic laws. This could increase the risk of a crash if the driver doesn't intervene. Corrective Actions: Tesla will notify owners by email and supply an over-the-air software update to improve how the FSD Beta feature maneuvers the vehicle in certain traffic situations. Tesla reminds that FSD Beta is only an advanced driver assistance feature, and the driver must pay attention and be ready to take control at all times when the feature is engaged.

### Electrical

2021038 29 Jan 2021

Issue: On certain vehicles, the internal memory for the media control unit (MCU) could run out of storage capacity over time. If this happens, the center display can turn off while driving and cause some of the car's systems not to work properly. This includes the rearview camera display, defrost/defog control settings, and exterior turn signal lighting. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. A windshield that cannot be defrosted/defogged could reduce visibility. Turn signals that do not work could cause a following driver not to recognize that a vehicle ahead intends to turn. These conditions could increase the risk of a crash. Corrective Actions: Tesla advises owners to ensure that their vehicle software is up to date. Tesla will notify owners by email, including when parts are available to schedule service to upgrade the internal memory in the MCU.

### Structure

2020553 17 Nov 2020

This recall was replaced by Transport Canada recall no. 2024-483. Issue: On certain vehicles, two of the cosmetic roof trims may not be properly attached. This includes the cosmetic roof trim just behind the top of the windshield and the spine cosmetic roof trim between the rear doors. Over time, these cosmetic roof trims could loosen and separate from the vehicle. Safety Risk: Cosmetic roof trims that detach from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Tesla will notify owners by mail and advise you to contact Tesla Service to arrange for a no-charge inspection of your vehicle. If the cosmetic roof trims are not properly attached, they will be re-installed.

4 more on the model-year record, cardog.app/tools/recalls/tesla/model-x/2016

> Listed for the model year, not checked against your VIN. Tesla confirms which apply.
> Check your VIN with Tesla or call a Tesla dealer with your VIN.
> service.tesla.com/en-CA/vin-recall-search

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $21,490[5], $8,505 under the median of $29,995[4].

| | |
|---|---|
| Lowest ask | $21,490 |
| Middle half | $23,498 – $31,384 |
| Median ask | $29,995 |
| This car | $21,490 |

Same model year · 11 live listings · as of 26 Oct 2026

### OTHER 2016 TESLA MODEL X LISTINGS [5]

| | |
|---|---|
| Oshawa, ON · 203,123 km | $21,425 |
| Scarborough, ON · 252,097 km | $23,000 |
| Toronto, ON · 86,000 km | $31,770 |
| Richmond, BC · 137,883 km | $30,999 |
| Toronto, ON · 128,828 km | $29,995 |
| Calgary, AB · 98,009 km | $27,999 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Fremont, California, United States |
| 20 Apr 2017 | Transport Canada recall 2017218[2]<br>Issued for the model year · Brakes |
| 12 Oct 2017 | Transport Canada recall 2017496[2]<br>Issued for the model year · Seats and restraints |
| 5 Feb 2020 | Transport Canada recall 2020038[2]<br>Issued for the model year · Steering |
| 20 Oct 2020 | Transport Canada recall 2020497[2]<br>Issued for the model year · Lights and instruments |
| 17 Nov 2020 | Transport Canada recall 2020553[2]<br>Issued for the model year · Structure |
| 29 Jan 2021 | Transport Canada recall 2021038[2]<br>Issued for the model year · Electrical |
| 14 Feb 2023 | Transport Canada recall 2023063[2]<br>Issued for the model year · Accessories |
| 12 Dec 2023 | Transport Canada recall 2023657[2]<br>Issued for the model year · Accessories |
| 21 May 2024 | Transport Canada recall 2024283[2]<br>Issued for the model year · Lights and instruments |
| 16 Aug 2024 | Transport Canada recall 2024483[2]<br>Issued for the model year · Structure |
| 25 Oct 2026 | Listed for sale, Fenwick, ON[5]<br>Japanese Sport Car · asking $21,490 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.