Register entry, as of 26 October 2026 Listed for sale Record ID d8bfdbef17d8

2009 Pontiac G8 Base

3.6 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

6G2	ER577	0	9	L	162144
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Pontiac · GENERAL MOTO…	G8 · 3.6 L	Computes	2009	Elizabeth	Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.6 L, 6 cylinders
Make	Pontiac	Fuel	Gasoline
Model	G8	Drive	Not in the decode
Trim	Base	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Elizabeth, South Australia, Australia

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/g8/2009

4 recalls listed by Transport Canada for this model year

Seats and restraints

2015274 18 Jun 2015

On certain vehicles, the flexible steel cable that connects the seat belt to the vehicle structure at the front outboard seating positions can fatigue over time and could separate, increasing the risk of injury in a crash. Correction: Dealers will replace the tensioner assembly.

Electrical

2014379 9 Sep 2014

On certain vehicles, there is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key from out of the "run" position. If this were to occur, engine power, power braking and power steering would be affected, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: Dealers will remove the key blade from the original flip key/transmitter assemblies provided with the vehicle, and will cut and fit the revised key blade and housing assembly, in which the blade has been indexed by 90 degrees to the original transmitter assembly. Important note: Until the correction is performed, drivers should adjust their seat and steering column to allow clearance between their knee and the ignition key.

Airbag

2011389 4 Nov 2011

On certain vehicles, when the front passenger seat is in the full forward position, the seat position sensor may cause a deployment delay between the first and second stages of the dual-stage front passenger airbag. Failure of the airbag to deploy as intended during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will reprogram the Sensing and Diagnostic Module.

Lights and instruments

2009146 22 May 2009

On certain vehicles, the brake pedal position switch may have been incorrectly programmed during vehicle assembly. As a result, the brake lamps may remain illuminated when the brake pedal is released. Failure of the brake lamps to operate as intended may result in the following road users being unaware of the driver's intentions, increasing the risk of a crash causing personal injury or death. Correction: Dealers will reprogram the brake position sensor.

> Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
> Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
> experience.gm.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,999[5], $5,951 under the median of $10,950[4].

Lowest ask	$4,999
Middle half	$7,974 – $13,925
Median ask	$10,950
This car	$4,999

Same model year · 2 live listings · as of 26 Oct 2026

§4 EVENTS

2009	Model year 2009[1] Assembly plant Elizabeth, South Australia, Australia
22 May 2009	Transport Canada recall 2009146[2] Issued for the model year · Lights and instruments
4 Nov 2011	Transport Canada recall 2011389[2] Issued for the model year · Airbag
9 Sep 2014	Transport Canada recall 2014379[2] Issued for the model year · Electrical
18 Jun 2015	Transport Canada recall 2015274[2] Issued for the model year · Seats and restraints
25 Oct 2026	Listed for sale, Pickering, ON[5] Star Line Sales and Leasing · asking $4,999

§5 DOCUMENTS

Window sticker This VIN reads as model year 2009, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.