Register entry, as of 29 October 2026 Listed for sale Record ID 9071932a3a94

2012 Mitsubishi RVR

2.0 L · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA4	AJ3AU	8	C	Z	600439
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mitsubishi Motors Corporat…	RVR · 2.0 L	Computes	2012	Okazaki	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.0 L
Make	Mitsubishi	Fuel	Gasoline
Model	RVR	Drive	4WD
Trim	Not in the decode	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sport Utility Vehicle	Plant	Okazaki, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/rvr/2012

7 recalls listed by Transport Canada for this model year

Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

Structure

2020216 15 May 2020

Issue: On certain vehicles, road salt can corrode the front cross-member (subframe). As a result, a lower control arm could eventually detach from the cross-member. This could cause a loss of vehicle control. Safety Risk: A loss of control can create the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front cross-member (subframe). If no significant corrosion is found, the dealer will spray a sealing and anti-corrosion coating both inside and on the cross-member. If significant corrosion is found, the dealer will replace the cross-member.

Visual system

2018083 12 Feb 2018

On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will inspect the wiper motor crank arm and replace as necessary.

Electrical

2018052 26 Jan 2018

On certain vehicles, the flange of the drive belt automatic tensioner may crack over time due to repetitive high load operations and stress concentration. This could cause the drive belt to detach, leading to battery depletion, which would result in a loss of motive power and a loss of power steering assist. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the auto tensioner with a countermeasure unit.

Structure

2016591 24 Nov 2016

On certain vehicles, the outer tubes of the rear liftgate support struts may have had insufficient anti-corrosion treatment applied during manufacturing. As a result, the outer tube could corrode due to salt and water penetration. If this were to occur, the liftgate support strut could rapidly lose pressure, which would allow the liftgate to drop suddenly, placing anyone beneath or near the gate at risk of injury. Correction: Dealers will replace the rear liftgate support struts with updated ones.

Visual system

2016530 27 Oct 2016

On certain vehicles, water may drain from the windshield cowl area and potentially collect in the area of the wiper motor breathing hole. If the wiper motor is not operating, water could potentially enter the wiper motor through the breathing hole. If this occurs, over time, it could result in corrosion and/or an electrical conduction failure, both of which could result in the wiper motor not operating. If the wiper motor were to stop operating, the windshield wipers would become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper motor with an upgraded wiper motor that will prevent water intrusion.

1 more on the model-year record, cardog.app/tools/recalls/mitsubishi/rvr/2012

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

§3 VALUE [3]

This car asks $7,850[4], $855 over the median of $6,995[3].

Lowest ask	$4,553
Middle half	$5,774 – $7,422
Median ask	$6,995
This car	$7,850

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2012 MITSUBISHI RVR LISTINGS [4]

Orangeville, ON · 253,000 km	$4,553
Sundridge, ON · 253,000 km	$4,553
Orangeville, ON · 253,000 km	$4,553
Orangeville, ON · 253,000 km	$4,553
Orangeville, ON · 253,000 km	$4,553
Huntsvillle, ON · 253,000 km	$4,553

§4 EVENTS

2012	Model year 2012[1] Assembly plant Okazaki, Japan
4 Jan 2012	Transport Canada recall 2012001[2] Issued for the model year · Lights and instruments
27 Oct 2016	Transport Canada recall 2016530[2] Issued for the model year · Visual system
24 Nov 2016	Transport Canada recall 2016591[2] Issued for the model year · Structure
26 Jan 2018	Transport Canada recall 2018052[2] Issued for the model year · Electrical
12 Feb 2018	Transport Canada recall 2018083[2] Issued for the model year · Visual system
15 May 2020	Transport Canada recall 2020216[2] Issued for the model year · Structure
19 Sep 2024	Transport Canada recall 2024554[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Sainte-Marie, QC[4] Blais Mazda · asking $7,850
29 Oct 2026	Listing last updated[4] asking $7,850

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.