Register entry, as of 27 October 2026 Listed for sale Record ID be3a814e3171

# 2017 Mitsubishi Outlander

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JA4 | AZ2A3 | 5 | H | Z | 601131 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mitsubishi Motors Corporat… | Outlander · 2.4 L | Computes | 2017 | Okazaki | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 2.4 L, 4 cylinders |
| Make | Mitsubishi | Fuel | Gasoline |
| Model | Outlander | Drive | 4WD |
| Trim | Not in the decode | Maker | Mitsubishi Motors Corporation (MMC) |
| Body | Sport Utility Vehicle | Plant | Okazaki, Aichi, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2017

**6** recalls listed by Transport Canada for this model year

### Structure

2025405 6 Aug 2025

Issue: On certain vehicles, water could enter the tailgate struts and cause them to corrode. If this happens, the struts could fail, and the tailgate could drop suddenly. Safety Risk: A tailgate that drops suddenly could increase the risk of injury. Corrective Actions: Mitsubishi will notify owners by mail and advise you to take your vehicle to a dealership to replace the tailgate struts.

### Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

### Seats and restraints

2020317 14 Jul 2020

Issue: On certain vehicles, the seat belt buckle for the right seat in the second-row could be damaged when the seats are folded down. This can cause the seat belt buckle cover to come off. If this happens, the seat belt may not latch properly. Safety Risk: A seat belt that does not latch properly could create an increased risk of injury in a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to modify the center seat belt buckle in the second seating row. A warning label will also be attached to the right seat base and additional instructions will be added to the owner's manual.

### Other

2018508 14 Sep 2018

On certain vehicles, an issue in the software that manages the brake system Hydraulic Unit may allow it to reset without warning and could cause some vehicle features to malfunction. If this were to occur while driving, the following features may be affected: automatic braking (if Automatic Cruise Control (ACC) and/or Forward Collision Mitigation (FCM) is in operation), Antilock Brake System (ABS), Active Stability Control (ASC), Brake Auto Hold (BAH). If these systems malfunction, there could be an increased risk of a crash causing injury and/or damage to property. Correction: Dealers will update the Hydraulic Unit control software.

### Other

2018507 14 Sep 2018

On certain vehicles, an issue in the software used by the Electronic Control Unit responsible for managing the Forward Collision Mitigation (FCM) feature may cause it to not operate as intended alerting the driver to brake unnecessarily in certain situations. If the driver attempts to brake while FCM is also activating, the vehicle may decelerate rapidly. This could create a situation where another motorist does not anticipate a preceding vehicle's sudden brake application or stop, creating the risk of a rear-end collision causing injury and/or damage to property. Correction: Dealers will update the software for the Forward Collision Mitigation system.

### Engine

2017475 29 Sep 2017

On certain vehicles, defective electrical relays may have been installed in the power distribution center. This could cause various electrical circuits to fail, potentially resulting in engine stalling, reduced engine power, or loss of engine cooling fan function potentially resulting in engine overheating. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace affected relay(s) with updated parts.

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,995[5], $341 under the median of $11,336[4].




| | |
|---|---|
| Lowest ask | $7,999 |
| Middle half | $10,371 – $14,333 |
| Median ask | $11,336 |
| This car | $10,995 |

Same configuration · 8 live listings · as of 27 Oct 2026

#### OTHER 2017 MITSUBISHI OUTLANDER LISTINGS [5]

| | |
|---|---|
| Mirabel, QC · 88,863 km | $13,992 |
| Calgary, AB · 119,606 km | $14,995 |
| Ascot Corner, QC · 94,290 km | $15,991 |
| Blainville, QC · 88,863 km | $13,992 |
| Whitby, ON · 89,693 km | $15,988 |
| Brossard, QC · 88,863 km | $13,992 |

## §4 EVENTS

2017 Model year 2017[1]
Assembly plant Okazaki, Aichi, Japan

| | |
|---|---|
| 29 Sep 2017 | Transport Canada recall 2017475[2]<br>Issued for the model year · Engine |
| 14 Sep 2018 | Transport Canada recall 2018508[2]<br>Issued for the model year · Other |
| 14 Sep 2018 | Transport Canada recall 2018507[2]<br>Issued for the model year · Other |
| 14 Jul 2020 | Transport Canada recall 2020317[2]<br>Issued for the model year · Seats and restraints |
| 19 Sep 2024 | Transport Canada recall 2024554[2]<br>Issued for the model year · Label |
| 6 Aug 2025 | Transport Canada recall 2025405[2]<br>Issued for the model year · Structure |
| 26 Oct 2026 | Listed for sale, Laval, QC[5]<br>groupeautomobile.com · asking $10,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $10,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.