Register entry, as of 29 November 2026 Listed for sale Record ID 77c6bec72525

2010 Mitsubishi Outlander

3.0 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JA4	JT5AX	5	A	Z	601142
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mitsubishi Motors Corporat…	Outlander · 3.0 L	Computes	2010	Okazaki	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	3.0 L, 6 cylinders
Make	Mitsubishi	Fuel	Gasoline
Model	Outlander	Drive	4WD
Trim	Not in the decode	Maker	Mitsubishi Motors Corporation (MMC)
Body	Sport Utility Vehicle	Plant	Okazaki, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/outlander/2010

12 recalls listed by Transport Canada for this model year

Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

Structure

2020216 15 May 2020

Issue: On certain vehicles, road salt can corrode the front cross-member (subframe). As a result, a lower control arm could eventually detach from the cross-member. This could cause a loss of vehicle control. Safety Risk: A loss of control can create the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front cross-member (subframe). If no significant corrosion is found, the dealer will spray a sealing and anti-corrosion coating both inside and on the cross-member. If significant corrosion is found, the dealer will replace the cross-member.

Accessories

2018054 26 Jan 2018

On certain vehicles, the sunroof may not have been bonded properly and could separate from the vehicle. This could pose a risk to other road users, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the sunroof glass assembly.

Electrical

2018052 26 Jan 2018

On certain vehicles, the flange of the drive belt automatic tensioner may crack over time due to repetitive high load operations and stress concentration. This could cause the drive belt to detach, leading to battery depletion, which would result in a loss of motive power and a loss of power steering assist. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the auto tensioner with a countermeasure unit.

Visual system

2017364 20 Jul 2017

On certain vehicles, water may drain from the windshield cowl area and potentially collect in the area of the wiper motor breathing hole. If the wiper motor is not operating, water could potentially enter the wiper motor through the breathing hole. If this occurs, over time, it could result in corrosion and/or an electrical conduction failure, both of which could result in the wiper motor not operating. If the wiper motor were to stop operating, the windshield wipers would become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper motor with an upgraded wiper motor that will prevent water intrusion.

Visual system

2016529 27 Oct 2016

On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the rubber boot which covers the ball joint with a countermeasure one, and the wiper motor crank arm will also be inspected and replaced as necessary.


6 more on the model-year record, cardog.app/tools/recalls/mitsubishi/outlander/2010

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,750[5], $1,351 over the median of $3,399[4].



Lowest ask	$1,900
Middle half	$2,166 – $4,562
Median ask	$3,399
This car	$4,750

Same model year · 6 live listings · as of 29 Nov 2026

OTHER 2010 MITSUBISHI OUTLANDER LISTINGS [5]

Newmarket, ON · 174,963 km	$3,998
Toronto, ON · 225,750 km	$1,900
Stouffville, ON · 205,730 km	$2,800
Longueuil, QC · 267,814 km	$1,955
Mount Hope, Hamilton, ON · 145,770 km	$4,998

§4 EVENTS

2010	Model year 2010[1] Assembly plant Okazaki, Japan
25 Jun 2014	Transport Canada recall 2014248[2] Issued for the model year · Powertrain
25 Jun 2014	Transport Canada recall 2014247[2] Issued for the model year · Steering
15 Sep 2014	Transport Canada recall 2014397[2] Issued for the model year · Engine
17 Apr 2015	Transport Canada recall 2015166[2] Issued for the model year · Heater and defroster
17 Apr 2015	Transport Canada recall 2015165[2] Issued for the model year · Lights and instruments
21 Jun 2016	Transport Canada recall 2016317[2] Issued for the model year · Structure
27 Oct 2016	Transport Canada recall 2016529[2] Issued for the model year · Visual system
20 Jul 2017	Transport Canada recall 2017364[2] Issued for the model year · Visual system
26 Jan 2018	Transport Canada recall 2018054[2] Issued for the model year · Accessories
26 Jan 2018	Transport Canada recall 2018052[2] Issued for the model year · Electrical
15 May 2020	Transport Canada recall 2020216[2] Issued for the model year · Structure
19 Sep 2024	Transport Canada recall 2024554[2] Issued for the model year · Label
24 Nov 2026	Listed for sale, Vaudreuil-Dorion, QC[5] Prilo Occasion · asking $4,750
29 Nov 2026	Listing last updated[5] asking $4,750

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.