Register entry, as of 29 October 2026 Listed for sale Record ID 47e0f82151f4

# 2016 Subaru Forester Touring + MR + NAVI(H/K) + ES + KA

2.0 L · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JF2 | SJHXC | 5 | G | H | 477380 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Subaru Corporation | Forester · 2.0 L | Computes | 2016 | Japan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 2.0 L |
| Make | Subaru | Fuel | Gasoline |
| Model | Forester | Drive | AWD |
| Trim | Touring + MR + NAVI(H/K) + ES + KA | Maker | SUBARU CORPORATION |
| Body | Sport Utility Vehicle | Plant | Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/forester/2016

**4** recalls listed by Transport Canada for this model year

### Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

### Airbag

2019492 4 Oct 2019

Issue: On certain vehicles, the passenger occupant detection system (ODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the ODS sensor mat harness. It will be replaced if necessary.

### Brakes

2019104 1 Mar 2019

Issue: On certain vehicles, the brake lamp switch could fail. This would cause the brake lamps not to turn on when the brakes are applied. Depending on the model, this could cause an inability to shift from park or to start using the push-button ignition. This may also cause problems with the following: anti-lock brake system (ABS), vehicle dynamics control (VDC), and/or Eyesight system. Safety Risk: If the brake lights do not work, a following driver may not to recognize that a vehicle ahead is braking, increasing the risk of crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the brake lamp switch replaced.

### Engine

2016122 17 Mar 2016

On certain vehicles, a portion of the engine turbocharger air intake duct may crack due to incorrect material being used during production. If the air intake duct were to crack, it could result in the engine developing a rough idle, reduced power and possibly a stall. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will inspect the engine turbocharger air intake duct, and replace as necessary.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $17,588[5], $3,639 over the median of $13,949[4].

| | |
|---|---|
| Lowest ask | $4,995 |
| Middle half | $11,844 – $16,916 |
| Median ask | $13,949 |
| This car | $17,588 |

Same model year · 36 live listings · as of 29 Oct 2026

OTHER 2016 SUBARU FORESTER LISTINGS [5]

| | |
|---|---|
| Markham, ON · 184,988 km | $10,888 |
| Victoria, BC · 108,656 km | $17,995 |
| Terrebonne, QC · 151,934 km | $10,977 |
| Sainte-Rose, QC · 146,484 km | $12,995 |
| Thorndale, ON · 336,951 km | $4,995 |
| Gloucester, ON · 133,152 km | $15,089 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Japan |
| 17 Mar 2016 | Transport Canada recall 2016122[2]<br>Issued for the model year · Engine |
| 1 Mar 2019 | Transport Canada recall 2019104[2]<br>Issued for the model year · Brakes |
| 4 Oct 2019 | Transport Canada recall 2019492[2]<br>Issued for the model year · Airbag |
| 15 Aug 2024 | Transport Canada recall 2024546[2]<br>Issued for the model year · Label |

| | |
|---|---|
| 17 Sep 2026 | Listed for sale, Oakville, ON[5]<br>Medallion Motors Inc · asking $17,588 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $17,588 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 36 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.