Register entry, as of 6 November 2026 Listed for sale Record ID 032b17df5aac

2008 Honda Fit

1.5 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JHM	GD384	X	8	S	813422
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Honda Motor Co., Ltd.	Fit · 1.5 L	Computes	2008	Suzuka	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Fit	Drive	Not in the decode
Trim	Not in the decode	Maker	HONDA MOTOR CO., LTD.
Body	Hatchback	Plant	Suzuka, Mie, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/fit/2008

6 recalls listed by Transport Canada for this model year

Powertrain

2020610 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

Airbag

2017009 10 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag inflator. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Steering

2014345 11 Aug 2014

On certain vehicles, a fault in the Electric Power Steering (EPS) system could result in an immediate loss of power steering assist without warning to the driver. This would unexpectedly increase the steering effort force necessary to steer the vehicle at lower vehicle speeds, which could increase the risk of a crash causing injury and/or damage to property. Correction: Vehicles will receive a special extended warranty coverage of 10 years/240,000 km from first registration. Under this special coverage program, vehicles which experience this condition will have the electric power steering module replaced.

Electrical

2013216 21 Jun 2013

On certain vehicles, water may enter the driver's power window master switch. Although Honda previously attempted to remedy this problem by installing a plastic cover over the switch, this fix was inadequate. Water intrusion could cause the switch to overheat, which may result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the driver's power window master switch. Note: This recall supersedes recall 2010025. Vehicles that were repaired under the previous campaign will also need to be repaired under this campaign.

Electrical

2010025 1 Feb 2010

On certain vehicles, under severe conditions water may enter the driver's window and reach the master power window switch. If the master power switch is damaged as a result of water intrusion it may result in a failure of the switch and overheating. An overheating switch can cause smoke, melting and fire which could result in property damage and personal injury. Correction: Dealers will install an external cover to prevent water from entering the switch. Damaged switches will be replaced and cover installed. Note: This recall is superseded by recall 2013216.

Other

2007388 5 Dec 2007


On certain vehicles, the wire harness for the Occupant Detection System (ODS) and the Occupant Position Detection System (OPDS) is routed underneath the carpet on the driver's side floorboard. In areas where road salt is used, salt from the snow on the drivers shoes will melt and may penetrate the carpet and leak into the wire harness. If the harness is exposed to salt brine, corrosion may occur and the wire may break causing the Safety Restraint System (SRS) indicator light to illuminate. A failure of the ODS and OPDS may not detect the presence of a child seat or an out-of-position passenger and deployment of both the front seat passenger's frontal and side airbags will not be suppressed. In the event of a crash, a deploying front passenger airbag or front passenger's side airbag will increase the risk of injury to small or out-of-position occupants. Correction: Dealers will inspect the wire harness. If there is no corrosion, the harness will be re-insulated; if corrosion is evident, the wire harness will be replaced.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,995[5], $5,015 over the median of $5,980[4].



Lowest ask	$5,800
Middle half	$5,890 – $8,488
Median ask	$5,980
This car	$10,995

Same model year · 3 live listings · as of 6 Nov 2026

OTHER 2008 HONDA FIT LISTINGS [5]

New Westminster, BC · 218,000 km	$5,980
Surrey, BC · 189,250 km	$5,800

§4 EVENTS

2008 **Model year 2008**[1]
Assembly plant Suzuka, Mie, Japan

5 Dec 2007	Transport Canada recall 2007388[2] Issued for the model year · Other
1 Feb 2010	Transport Canada recall 2010025[2] Issued for the model year · Electrical
21 Jun 2013	Transport Canada recall 2013216[2] Issued for the model year · Electrical
11 Aug 2014	Transport Canada recall 2014345[2] Issued for the model year · Steering
10 Jan 2017	Transport Canada recall 2017009[2] Issued for the model year · Airbag
10 Dec 2020	Transport Canada recall 2020610[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, Kelowna, BC[5] Harmony Honda · asking $10,995
4 Nov 2026	Listing last updated[5] asking $10,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 6 Nov 2026
[5] Live public dealer listings on Cardog, as of 6 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.