Register entry, as of 17 November 2026 Listed for sale Record ID aa36e61da510

2007 Lexus IS 250 AWD

2.5 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH	CK262	4	7	2	014685
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lexus · TOYOTA MOTOR C…	IS · 2.5 L	Computes	2007	Japan	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	2.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	IS	Drive	AWD
Trim	250 AWD	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/is/2007

9 recalls listed by Transport Canada for this model year

Fuel system

2018346 26 Jun 2018

On certain vehicles equipped with a 3.5L V6 engine, the fuel pulsation dampers located in the fuel delivery pipe could develop a leak over time. A fuel leak in the presence of an ignition source could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will replace the fuel delivery pipe with an updated part.

Airbag

2017007 9 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Depending on the model, dealers will either replace the passenger frontal airbag inflator or airbag assembly. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Fuel system

2014458 16 Oct 2014

On certain vehicles, the fuel delivery pipes in the engine compartment may have been produced with particles from the anti-corrosion plating on the gasket seating surface where the fuel pressure sensor is installed. This could affect the sealing properties of the gasket seated between the pressure sensor and the pipe, potentially resulting in a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will replace the gasket and repair the gasket seating surface.

Engine

2013297 4 Sep 2013

On certain vehicles, the bolts used to secure the housing and sprocket of the intake-side Variable-Valve Timing (VVT) gear assembly could loosen. If this occurs, the VVT gear will not control the intake valves correctly. In some instances, the VVT gear housing and sprocket could separate, causing the engine to stall. Engine stalling would result in a loss of vehicle propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the VVT unit with an improved version.

Visual system

2013031 30 Jan 2013

On certain vehicles, the wiper arm securing nuts could have been insufficiently tightened during assembly. If the movement of the wipers is restricted by an external load, such as heavy snow on the windshield, the wiper arms could slip and one or both wipers could become inoperative. If this occurs, driver visibility could be reduced, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will clean the mating surface of the wiper arm and motor shaft and install improved wiper arm nuts.

Fuel system

2011037 26 Jan 2011

On certain GS 300, GS 300 AWD, GS 350, IS 250, IS 250 AWD and IS 350 vehicles, the fuel pressure sensor connected to the engine fuel delivery pipe may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and pipe, and through the threaded portion of the sensor. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect for fuel leakage from the threaded portion of the fuel pressure sensor. If there are no signs of a fuel leak, the fuel pressure sensor will be tightened to specifications. If a fuel leak is confirmed, the gasket between the sensor and the fuel delivery pipe will be replaced, and the sensor will be tightened.

3 more on the model-year record, cardog.app/tools/recalls/lexus/is/2007

> Listed for the model year, not checked against your VIN. Lexus confirms which apply.
> Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.
> www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,900[5], $2,000 over the median of $11,900[4].



Lowest ask	$10,999
Middle half	$11,450 – $12,900
Median ask	$11,900
This car	$13,900

Same model year · 3 live listings · as of 15 Nov 2026

§4 EVENTS

2007	Model year 2007[1] Assembly plant Japan
19 Jan 2009	Transport Canada recall 2009015[2] Issued for the model year · Fuel system
7 Oct 2009	Transport Canada recall 2009290[2] Issued for the model year · Other

5 Jul 2010	Transport Canada recall 2010221[2]	Issued for the model year · Engine
26 Jan 2011	Transport Canada recall 2011037[2]	Issued for the model year · Fuel system
30 Jan 2013	Transport Canada recall 2013031[2]	Issued for the model year · Visual system
4 Sep 2013	Transport Canada recall 2013297[2]	Issued for the model year · Engine
16 Oct 2014	Transport Canada recall 2014458[2]	Issued for the model year · Fuel system
9 Jan 2017	Transport Canada recall 2017007[2]	Issued for the model year · Airbag
26 Jun 2018	Transport Canada recall 2018346[2]	Issued for the model year · Fuel system
13 Nov 2026	Listed for sale, Edmonton, AB[5]	Diamond Motors · asking $13,900
17 Nov 2026	Listing last updated[5]	asking $13,900

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 3 live listings, as of 15 Nov 2026

[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.