Register entry, as of 28 October 2026 Listed for sale Record ID a1f961c350b6

# 2014 Buick Encore Leather

1.4 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KL4 | CJGSB | 1 | E | B | 764298 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Buick · GENERAL MOTORS… | Encore · 1.4 L | Computes | 2014 | Bupyeong | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 1.4 L, 4 cylinders |
| Make | Buick | Fuel | Gasoline |
| Model | Encore | Drive | AWD |
| Trim | Leather | Maker | GENERAL MOTORS LLC |
| Body | Sport Utility Vehicle | Plant | Bupyeong, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/encore/2014

**4** recalls listed by Transport Canada for this model year

### Airbag

2016439 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014-2017 model year Sierra LD/Silverado LD models and 2015-2016 model year Sierra HD/Silverado HD model vehicles.

### Seats and restraints

2014315 29 Jul 2014

On certain vehicles, the hook bracket assembly for either front seat may have been manufactured with an incomplete weld. If the weld is incomplete and the assembly is exposed to a high load condition, the hook may separate from the seat track. This could increase the risk of occupant injury during a crash. Correction: Dealers will inspect the weld, and if necessary, replace the lower seat track.

### Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

### Label

2014014 21 Jan 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 115 - Vehicle Identification Number. The character height is insufficient for the vehicle identification number located on the front dashboard cover. Correction: No corrective recall action is required as this technical non-compliance is deemed to be non-safety related.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $9,657[5], $121 under the median of $9,778[4].

| | |
|---|---|
| Lowest ask | $5,950 |
| Middle half | $7,366 – $10,247 |
| Median ask | $9,778 |
| This car | $9,657 |

Same model year · 16 live listings · as of 28 Oct 2026

### OTHER 2014 BUICK ENCORE LISTINGS [5]

| | |
|---|---|
| Hamilton, ON · 140,000 km | $9,995 |
| Cambridge, ON · 168,692 km | $9,989 |
| Calgary, AB · 116,287 km | $14,999 |
| Barrie, ON · 146,678 km | $10,990 |
| Grande Prairie, AB · 146,145 km | $7,489 |
| Hamilton, ON · 119,000 km | $10,995 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Bupyeong, South Korea |
| 21 Jan 2014 | Transport Canada recall 2014014[2]<br>Issued for the model year · Label |
| 3 Jul 2014 | Transport Canada recall 2014274[2]<br>Issued for the model year · Accessories |
| 29 Jul 2014 | Transport Canada recall 2014315[2]<br>Issued for the model year · Seats and restraints |
| 9 Sep 2016 | Transport Canada recall 2016439[2]<br>Issued for the model year · Airbag |
| 23 Jun 2026 | Listed for sale, St-Hubert, QC[5]<br>Clairmount Auto St-Hubert · asking $9,657 |

| | |
|---|---|
| 28 Oct 2026 | Listing last updated[5]<br>asking $9,657 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 16 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.