Register entry, as of 27 October 2026 Listed for sale Record ID f12d0438f375

# 2020 Hyundai Kona SEL

4x2 · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | K23AG | 5 | L | U | 060557 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Kona | Computes | 2020 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | Not in the decode |
| Make | Hyundai | Fuel | Electric |
| Model | Kona | Drive | 4x2 |
| Trim | SEL | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2020

**7** recalls listed by Transport Canada for this model year

### Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Engine

2021252 28 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. Hyundai is also developing a Piston-ring Noise Sensing System (PNSS) software update to be installed when available; it will alert the driver of potential damage before an engine failure occurs.

### High voltage

2021109 1 Mar 2021

Issue: On certain electric vehicles, there could be a problem inside the high-voltage battery. As a result, the high-voltage battery could short circuit while the vehicle is parked, charging, or driving. Note: Vehicles that had a battery replacement after completion of Hyundai recall R0175 (Transport Canada Recall No. 2020-477) do not require repair under this recall. For the Hyundai Ioniq, only certain all-electric models are affected by this recall. Safety Risk: A short circuit in the battery could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you bring your vehicle to a dealer to lower the battery charging limit to 80% until the final repair is available. You will also be provided with instructions for how to do this yourself using the vehicle's infotainment system. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or buildings until the battery charging limit is changed. The second step of this recall will be to replace the high-voltage battery (BSA). Hyundai will notify you when a replacement battery is available for your vehicle. <a href=https://www.r0183info.ca/>Click here for more information. </a>

### Brakes

2020593 2 Dec 2020

Issue: On certain vehicles, an abnormal sensor signal to the Integrated Electronic Brake (IEB) system could cause a sudden reduction in braking performance. If this happens, a brake warning light will turn on in the instrument cluster. Safety Risk: Reduced brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to update the IEB system software.

### High voltage

2020477 13 Oct 2020

Issue: On certain vehicles, there could be problems with the high-voltage battery that cannot be detected by the battery management system (BMS). As a result, the high-voltage battery could short circuit after it is fully charged. Safety Risk: A short circuit in the battery could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection. The high-voltage battery will be replaced, if necessary. The dealer will also update the BMS software to better detect battery problems. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or buildings until the recall repairs are completed.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/kona/2020

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $13,999[5], $3,893 under the median of $17,892[4].




| | |
|---|---|
| Lowest ask | $8,990 |
| Middle half | $15,988 – $19,904 |
| Median ask | $17,892 |
| This car | $13,999 |

Same model year · 96 live listings · as of 27 Oct 2026

### OTHER 2020 HYUNDAI KONA LISTINGS [5]

| | |
|---|---|
| Beauport, QC · 80,482 km | $17,495 |
| Calgary, AB · 82,173 km | $19,995 |
| Newmarket, ON · 93,723 km | $15,991 |
| Orleans, ON · 109,003 km | $17,288 |
| Maple Ridge, BC · 136,313 km | $20,327 |
| Maple Ridge, BC · 110,370 km | $18,908 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Ulsan, South Korea |
| 20 Jan 2020 | Transport Canada recall 2020016[2]<br>Issued for the model year · Label |
| 13 Oct 2020 | Transport Canada recall 2020477[2]<br>Issued for the model year · High voltage |
| 2 Dec 2020 | Transport Canada recall 2020593[2]<br>Issued for the model year · Brakes |
| 1 Mar 2021 | Transport Canada recall 2021109[2]<br>Issued for the model year · High voltage |
| 28 Apr 2021 | Transport Canada recall 2021252[2]<br>Issued for the model year · Engine |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 17 Nov 2025 | Transport Canada recall 2025636[2]<br>Issued for the model year · Other |
| 11 Sep 2026 | Listed for sale, Surrey, BC[5]<br>Value Motors And Car Rentals · asking $13,999 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $13,999 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 96 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.