Register entry, as of 29 October 2026 Listed for sale Record ID adc14a7af7b7

2020 Hyundai Kona SEL Plus

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8	K6CAA	X	L	U	517072
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Kona · 2.0 L	Computes	2020	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Kona	Drive	4WD
Trim	SEL Plus	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2020

7 recalls listed by Transport Canada for this model year

Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Engine

2021252 28 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. Hyundai is also developing a Piston-ring Noise Sensing System (PNSS) software update to be installed when available; it will alert the driver of potential damage before an engine failure occurs.

High voltage

2021109 1 Mar 2021

Issue: On certain electric vehicles, there could be a problem inside the high-voltage battery. As a result, the high-voltage battery could short circuit while the vehicle is parked, charging, or driving. Note: Vehicles that had a battery replacement after completion of Hyundai recall R0175 (Transport Canada Recall No. 2020-477) do not require repair under this recall. For the Hyundai Ioniq, only certain all-electric models are affected by this recall. Safety Risk: A short circuit in the battery could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you bring your vehicle to a dealer to lower the battery charging limit to 80% until the final repair is available. You will also be provided with instructions for how to do this yourself using the vehicle's infotainment system. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or buildings until the battery charging limit is changed. The second step of this recall will be to replace the high-voltage battery (BSA). Hyundai will notify you when a replacement battery is available for your vehicle. Click here for more information.

Brakes

2020593 2 Dec 2020

Issue: On certain vehicles, an abnormal sensor signal to the Integrated Electronic Brake (IEB) system could cause a sudden reduction in braking performance. If this happens, a brake warning light will turn on in the instrument cluster. Safety Risk: Reduced brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to update the IEB system software.

High voltage

2020477 13 Oct 2020

Issue: On certain vehicles, there could be problems with the high-voltage battery that cannot be detected by the battery management system (BMS). As a result, the high-voltage battery could short circuit after it is fully charged. Safety Risk: A short circuit in the battery could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection. The high-voltage battery will be replaced, if necessary. The dealer will also update the BMS software to better detect battery problems. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or buildings until the recall repairs are completed.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/kona/2020

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,995[5], $2,849 over the median of $18,146[4].

Lowest ask	$12,599
Middle half	$15,999 – $20,078
Median ask	$18,146
This car	$20,995

Same configuration · 20 live listings · as of 29 Oct 2026

OTHER 2020 HYUNDAI KONA LISTINGS [5]

Victoriaville, QC · 73,726 km	$17,995
Winnipeg, MB · 81,469 km	$17,998
Sept-Îles, QC · 55,852 km	$19,420
Kelowna, BC · 39,739 km	$21,727
Laval, QC · 190,049 km	$11,491
Victoria, BC · 39,739 km	$21,727

§4 EVENTS

2020	Model year 2020[1] Assembly plant Ulsan, South Korea
20 Jan 2020	Transport Canada recall 2020016[2] Issued for the model year · Label
13 Oct 2020	Transport Canada recall 2020477[2] Issued for the model year · High voltage
2 Dec 2020	Transport Canada recall 2020593[2] Issued for the model year · Brakes
1 Mar 2021	Transport Canada recall 2021109[2] Issued for the model year · High voltage
28 Apr 2021	Transport Canada recall 2021252[2] Issued for the model year · Engine
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
17 Nov 2025	Transport Canada recall 2025636[2] Issued for the model year · Other
28 Oct 2026	Listed for sale, Granby, QC[5] Hyundai Granby · asking $20,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 20 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.