Register entry, as of 29 October 2026 Listed for sale Record ID 3d90c4ea8144

2010 Hyundai Elantra Touring GLS

2.0 L, 4 cylinders · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	DC8AE	2	A	U	062779
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Elantra Touring · 2.0 L	Computes	2010	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra Touring	Drive	Not in the decode
Trim	GLS	Maker	HYUNDAI MOTOR CO
Body	Wagon	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra-touring/2010

5 recalls listed by Transport Canada for this model year

Brakes — 2020045 — 7 Feb 2020

Issue: On certain vehicles equipped with an anti-lock brake system (ABS), moisture can enter the ABS control module and cause a short circuit. Safety Risk: A short circuit could create a fire risk. This can happen even if the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to install a relay to power off the ABS control module when the vehicle is turned off.

Airbag — 2019542 — 29 Oct 2019

Issue: On certain cars, there may be a problem in the airbag control unit that can cause with airbags to deploy without a crash. As a result, the front airbags and seat belt pretensioners could deploy when the vehicle is stopped or moving at slow speeds. Safety Risk: Airbags or seat belt pretensioners that deploy without a crash could create a risk of injury and may also increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your car to a dealer to update the software for the airbag control unit.

Steering — 2015089 — 27 Feb 2015

Certain vehicles equipped with electric power steering (EPS) may experience a sudden loss of power steering assist that could occur at any time while driving. If the electronic control unit (ECU) were to sense a discrepancy in the torque sensing circuitry of the steering system, and indicator lamp would illuminate in the instrument cluster to inform the driver that steering assist is no longer provided. Steering control could be maintained, as the vehicle will revert to a manual steering mode, but would require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will update the electric power steering (EPS) control unit.

Structure

2014227 12 Jun 2014

On certain vehicles equipped with side curtain air bags, a bracket securing the headliner could become dislodged during side curtain airbag deployment and be propelled toward vehicle occupants, increasing the risk of injury. Correction: Dealers will install industrial adhesive strips to the vehicle headliner.

Electrical

2013325 25 Sep 2013

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,495[5], the median[4].

Lowest ask	$1,500
Middle half	$2,998 – $5,995
Median ask	$4,495
This car	$4,495

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2010 HYUNDAI ELANTRA TOURING LISTINGS [5]

Truro, NS · 283,007 km	$1,500
London, ON · 167,900 km	$7,495

§4 EVENTS

2010	Model year 2010[1] Assembly plant Ulsan, South Korea
25 Sep 2013	Transport Canada recall 2013325[2] Issued for the model year · Electrical
12 Jun 2014	Transport Canada recall 2014227[2] Issued for the model year · Structure
27 Feb 2015	Transport Canada recall 2015089[2] Issued for the model year · Steering
29 Oct 2019	Transport Canada recall 2019542[2] Issued for the model year · Airbag
7 Feb 2020	Transport Canada recall 2020045[2] Issued for the model year · Brakes

25 Oct 2026	Listed for sale, London, ON[5] Tiger Auto Sales Ltd. · asking $4,495
29 Oct 2026	Listing last updated[5] asking $4,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.