Register entry, as of 28 November 2026 Listed for sale Record ID d7eb2b640368

2012 Hyundai Veloster GLS(Middle grade)

1.6 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	TC6AD	0	C	U	075623
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Veloster · 1.6 L	Computes	2012	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Veloster	Drive	Not in the decode
Trim	GLS(Middle grade)	Maker	HYUNDAI MOTOR CO
Body	Coupe	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/veloster/2012

7 recalls listed by Transport Canada for this model year

Brakes 2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes 2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Electrical 2023102 28 Feb 2023

Issue: On certain vehicles, the rear parking assist sensors (mounted in the rear bumper) could short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to replace the rear parking assist sensor fuse and any defective sensors. Hyundai recommends that if the instrument cluster does not work, the transmission shifter is stuck in park, or if you see melted plastic on the rear bumper, you should park the vehicle outside and contact a Hyundai dealer.

Engine

2021674 4 Nov 2021

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects Santa Fe models equipped with a 2.4 L MPI engine, and Veloster models with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Brakes

2012419 11 Dec 2012

On certain vehicles, infiltration of moisture and road grime into the parking brake mechanism may eventually lead to corrosion and failure. As such, this may result in rear brake noise, the parking brake not releasing, or the inability to properly apply the parking brake. Should the vehicle be parked on a sufficient slope, the inability to apply the parking brake could result in unintended vehicle movement, which could cause a crash resulting in property damage and/or personal injury. Correction: Dealers will replace the rear brake caliper assemblies.

Other

2012418 11 Dec 2012

On certain vehicles, the panoramic sunroof glass may have been damaged during an automated assembly procedure at the factory. This damage may result in subsequent fracture of the sunroof glass. Sunroof glass panel breakage, while the vehicle is in motion, could cause driver distraction, which could result in a crash causing property damage and/or personal injury. Additionally, broken glass inside the vehicle poses a risk of injury to vehicle occupants. Correction: Dealers will inspect and, if necessary, replace the panoramic sunroof glass assembly.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/veloster/2012

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,994[5], $1,847 over the median of $4,147[4].



Lowest ask	$1,500
Middle half	$1,500 – $5,590
Median ask	$4,147
This car	$5,994

Same configuration · 8 live listings · as of 27 Nov 2026

OTHER 2012 HYUNDAI VELOSTER LISTINGS [5]

Okotoks, AB · 157,670 km	$1,180
Duncan, BC · 242,541 km	$1,500
Ottawa, ON · 214,830 km	$1,500
Longueuil, QC · 168,039 km	$5,455
Québec, QC · 191,200 km	$4,495
Sainte-Rose, QC · 171,037 km	$3,799

§4 EVENTS

2012	Model year 2012[1] Assembly plant Ulsan, South Korea
26 Sep 2011	Transport Canada recall 2011350[2] Issued for the model year · Lights and instruments
11 Dec 2012	Transport Canada recall 2012419[2] Issued for the model year · Brakes
11 Dec 2012	Transport Canada recall 2012418[2] Issued for the model year · Other
4 Nov 2021	Transport Canada recall 2021674[2] Issued for the model year · Engine
28 Feb 2023	Transport Canada recall 2023102[2] Issued for the model year · Electrical
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, Cowansville, QC[5] Ford Deragon · asking $5,994
26 Nov 2026	Listing last updated[5] asking $5,994

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 27 Nov 2026

[5] Live public dealer listings on Cardog, as of 28 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.