Register entry, as of 27 October 2026 Listed for sale Record ID 9782360fb62f

2017 Kia Niro Touring / Touring Tech

1.6 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	CE3LC	X	H	5	095171
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Niro · 1.6 L	Computes	2017	Hwasung	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.6 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Niro	Drive	4x2
Trim	Touring / Touring Tech	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Hwasung, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/niro/2017

5 recalls listed by Transport Canada for this model year

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Powertrain

2023423 1 Aug 2023

Issue: On certain vehicles, fluid could leak onto the printed circuit board for the hydraulic clutch actuator (HCA). If this happens, the circuit board could short circuit. Safety Risk: A short circuit could create the risk of an engine compartment fire while driving. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the hydraulic clutch actuator (HCA), and replace it if necessary. The technician will also install a new fuse for the HCA to reduce the risk of a fire.

Electrical

2018537 28 Sep 2018

On certain vehicles, the main relay contacts in the Power Relay Assembly located underneath the rear seat may have an inadequate connection. This could increase electrical resistance and generate heat, increasing the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect the Power Relay Assembly for signs of thermal damage. If no thermal damage is found, the main relay will be replaced. If signs of thermal damage exist, the Power Relay Assembly will be replaced. Note: This problem may cause the Illumination of the HEV warning light while driving and/or an inability to start the vehicle.

Engine

2018218 1 May 2018

On certain vehicles, the hydraulic clutch actuator (HCA) was produced with burrs that could damage the inner oil seal. A damaged oil seal may create an oil leak that could result in an accumulation of oil in the phase cap area, and eventually cause an electrical short. This could increase the risk of an engine compartment fire causing injury and/or damage to property. Correction: Dealers will inspect and, if necessary, replace the hydraulic clutch actuator. Note: This condition would result in the “HEV” warning light to illuminate.

Steering

2017168 23 Mar 2017

On certain vehicles, a connection at the electric power steering (EPS) motor may have been damaged at time of assembly. This could lead to a loss of the steering assist. A loss of power steering assist could unexpectedly increase steering effort which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the EPS motor.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,295[5], $2,648 over the median of $12,647[4].



Lowest ask	$7,998
Middle half	$9,499 – $15,970
Median ask	$12,647
This car	$15,295

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2017 KIA NIRO LISTINGS [5]

Oakville, ON · 183,338 km	$9,999
Chambly, QC · 295,089 km	$7,998

§4 EVENTS

2017	Model year 2017[1] Assembly plant Hwasung, South Korea
23 Mar 2017	Transport Canada recall 2017168[2] Issued for the model year · Steering
1 May 2018	Transport Canada recall 2018218[2] Issued for the model year · Engine
28 Sep 2018	Transport Canada recall 2018537[2] Issued for the model year · Electrical
1 Aug 2023	Transport Canada recall 2023423[2] Issued for the model year · Powertrain

15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
29 Jul 2026	Listed for sale, Mirabel, QC[5] Auto Studio 72 · asking $15,295
26 Oct 2026	Listing last updated[5] asking $15,295

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.