Register entry, as of 28 October 2026 Listed for sale Record ID 3cf00e1da444

2020 Jaguar I-PACE HSE

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

SAD	HD2S1	6	L	1	602249
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	I-PACE	Computes	2020	Graz	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	Not in the decode
Make	Jaguar	Fuel	Electric
Model	I-PACE	Drive	AWD
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Graz, Austria

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jaguar/i-pace/2020

6 recalls listed by Transport Canada for this model year

High voltage

2026049 5 Feb 2026

Issue: On certain vehicles, the recall repairs completed by a Jaguar dealer during Transport Canada recall nos. 2023-302, 2023-564 and 2024-073 may not be effective. As a result, another repair is required. On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Jaguar recommends that you charge and park your vehicle outside and away from other vehicles or buildings until the recall repairs are completed. As an interim repair, a dealer will update the vehicle software to limit the maximum charge setting at 90% until the recall repairs are available. Once the final repair is available, Jaguar will notify you by mail. The corrective actions for this recall are under development.

High voltage

2024073 8 Feb 2024

Issue: On a small number of vehicles, the recall repairs completed by a Jaguar dealer during recall H441 (Transport Canada recall number 2023-302) may not have been done correctly. As a result, a second repair is required. On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: Jaguar will notify owners by mail and advise you to take your vehicle to a dealership to install a software update for the battery energy control module. This software will monitor the high-voltage battery and warn you if it detects a problem. If this happens, the software will reduce the charging capacity to 75% and direct you to bring your vehicle to a dealership to inspect and, if necessary, replace the battery module and/or pack. Jaguar recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

High voltage

2023564 19 Oct 2023

Issue: On certain vehicles, the recall repairs completed by a Jaguar dealer during recall H441 (Transport Canada recall number 2023-302) may not have been done correctly. As a result, a second repair is required. On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: Jaguar will notify owners by mail and advise you to take your vehicle to a dealership to install a software update for the battery energy control module. This software will monitor the high-voltage battery and warn you if it detects a problem. If this happens, the software will reduce the charging capacity to 75% and direct you to bring your vehicle to a dealership to inspect and, if necessary, replace the battery module and/or pack. Jaguar recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

Heater and defroster

2023413 27 Jul 2023

Issue: On certain vehicles, the high-voltage coolant heater could fail. If this happens, you may experience reduced cabin heat, and the windshield defrost system may not work properly. Note: This recall only affects vehicles without a heated windshield. Safety Risk: A windshield defroster that doesn't work may cause reduced visibility and increase the risk of a crash. Corrective Actions: Jaguar Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the high-voltage coolant heater.

High voltage

2023302 25 May 2023

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: Jaguar will notify owners by mail and provide a software update for the battery energy control module. Jaguar recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed. For 2021 and newer vehicles, Jaguar send a wireless over-the-air software update to each vehicle. For 2019 and 2020 models, Jaguar will instruct you to schedule an appointment to have the update performed by a dealer. This software will monitor the high-voltage battery and warn you if it detects a problem. If this happens, the software will reduce the charging capacity to 75% and direct you to bring your vehicle to a dealership to inspect and, if necessary, replace the battery module and/or pack.

Brakes

2019219 9 May 2019

Issue: If there is a failure of the electrical regenerative braking system, there may be a delay before the brakes apply. Safety Risk: Reduced braking could cause extended stopping distances and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the vehicle software.

> Listed for the model year, not checked against your VIN. Jaguar confirms which apply.
> Check your VIN with Jaguar Canada or call a Jaguar dealer with your VIN.
> www.jaguar.com/en-ca/jdx/ownership/vin-recall.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $37,985[5], $7,037 over the median of $30,948[4].



Lowest ask	$28,990
Middle half	$29,747 – $33,420
Median ask	$30,948
This car	$37,985

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2020 JAGUAR I-PACE LISTINGS [5]

Richmond Hill, ON · 0 km	$29,999
Vaughan, ON · 42,089 km	$31,898
Mississauga, ON · 24,737 km	$28,990

§4 EVENTS

2020	Model year 2020[1] Assembly plant Graz, Austria
9 May 2019	Transport Canada recall 2019219[2] Issued for the model year · Brakes
25 May 2023	Transport Canada recall 2023302[2] Issued for the model year · High voltage
27 Jul 2023	Transport Canada recall 2023413[2] Issued for the model year · Heater and defroster
19 Oct 2023	Transport Canada recall 2023564[2] Issued for the model year · High voltage
8 Feb 2024	Transport Canada recall 2024073[2] Issued for the model year · High voltage
12 Mar 2025	Listed for sale, Winnipeg, MB[5] Auto List Of Canada · asking $37,985
5 Feb 2026	Transport Canada recall 2026049[2] Issued for the model year · High voltage
28 Oct 2026	Listing last updated[5] asking $37,985

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.