Register entry, as of 27 October 2026 Listed for sale Record ID 3dba6ff20b09

2023 Land Rover Discovery S R-Dynamic

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	RT2EX	8	P	2	486189
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Discovery · 2.0 L	Computes	2023	Nitra	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery	Drive	AWD
Trim	S R-Dynamic	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Nitra, Slovakia

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery/2023

7 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

Visual system

2026345 16 Jul 2026

Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display properly or at all. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera. The dealer will also add drainage holes to the tailgate trim.

Airbag

2026292 12 Jun 2026

Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.

High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

Engine

2023039 2 Feb 2023

Issue: On certain vehicles, an oil channel in the engine camshaft carrier wasn't drilled correctly. As a result, a buildup of oil pressure could cause an oil leak. Safety Risk: An engine oil leak can create the risk of a fire. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the camshaft carrier and replace it, if necessary. The dealer will also replace the catalytic converter, gasoline particulate filter (GPF) and exhaust oxygen sensors, as necessary.

1 more on the model-year record, cardog.app/tools/recalls/land-rover/discovery/2023

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $57,900[5], $9,458 over the median of $48,442[4].



Lowest ask	$37,989
Middle half	$43,496 – $57,900
Median ask	$48,442
This car	$57,900

Same model year · 8 live listings · as of 27 Oct 2026

OTHER 2023 LAND ROVER DISCOVERY LISTINGS [5]

Vancouver, BC · 68,547 km	$48,995
Vancouver, ON · 68,547 km	$48,995
North Vancouver, BC · 68,547 km	$48,995
Vancouver, BC · 68,547 km	$48,995
North Vancouver, BC · 68,547 km	$48,995
Vancouver, BC · 68,547 km	$48,995

§4 EVENTS

2023	Model year 2023[1] Assembly plant Nitra, Slovakia
21 Jul 2022	Transport Canada recall 2022392[2] Issued for the model year · Seats and restraints
2 Feb 2023	Transport Canada recall 2023039[2] Issued for the model year · Engine
10 Oct 2024	Transport Canada recall 2024599[2] Issued for the model year · Engine
17 Apr 2026	Transport Canada recall 2026196[2] Issued for the model year · High voltage
12 Jun 2026	Transport Canada recall 2026292[2] Issued for the model year · Airbag
15 Jun 2026	Listed for sale, Laval, QC[5] Jaguar Land Rover Laval · asking $57,900
16 Jul 2026	Transport Canada recall 2026345[2] Issued for the model year · Visual system
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
27 Oct 2026	Listing last updated[5] asking $57,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.