Register entry, as of 28 October 2026 Listed for sale Record ID 133a060a2692

# 2023 Land Rover Discovery S R-Dynamic

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| SAL | RT4EU | 9 | P | 2 | 479818 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jaguar Land Rover Limited | Discovery · 3.0 L | Computes | 2023 | Nitra | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.0 L, 6 cylinders |
| Make | Land Rover | Fuel | Gasoline |
| Model | Discovery | Drive | AWD |
| Trim | S R-Dynamic | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Nitra, Slovakia |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery/2023

**7** recalls listed by Transport Canada for this model year

### High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

### Visual system

2026345 16 Jul 2026

Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display properly or at all. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera. The dealer will also add drainage holes to the tailgate trim.

### Airbag

2026292 12 Jun 2026

Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.

### High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

### Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

### Engine

2023039 2 Feb 2023

Issue: On certain vehicles, an oil channel in the engine camshaft carrier wasn't drilled correctly. As a result, a buildup of oil pressure could cause an oil leak. Safety Risk: An engine oil leak can create the risk of a fire. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the camshaft carrier and replace it, if necessary. The dealer will also replace the catalytic converter, gasoline particulate filter (GPF) and exhaust oxygen sensors, as necessary.

1 more on the model-year record, cardog.app/tools/recalls/land-rover/discovery/2023

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $43,995[5], $5,000 under the median of $48,995[4].

| | |
|---|---|
| Lowest ask | $37,989 |
| Middle half | $43,995 – $57,900 |
| Median ask | $48,995 |
| This car | $43,995 |

Same model year · 9 live listings · as of 28 Oct 2026

### OTHER 2023 LAND ROVER DISCOVERY LISTINGS [5]

| | |
|---|---|
| Vancouver, BC · 68,547 km | $48,995 |
| Vancouver, ON · 68,547 km | $48,995 |
| North Vancouver, BC · 68,547 km | $48,995 |
| Vancouver, BC · 68,547 km | $48,995 |
| North Vancouver, BC · 68,547 km | $48,995 |
| Vancouver, BC · 68,547 km | $48,995 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Nitra, Slovakia |
| 21 Jul 2022 | Transport Canada recall 2022392[2]<br>Issued for the model year · Seats and restraints |
| 2 Feb 2023 | Transport Canada recall 2023039[2]<br>Issued for the model year · Engine |
| 10 Oct 2024 | Transport Canada recall 2024599[2]<br>Issued for the model year · Engine |
| 17 Apr 2026 | Transport Canada recall 2026196[2]<br>Issued for the model year · High voltage |
| 12 Jun 2026 | Transport Canada recall 2026292[2]<br>Issued for the model year · Airbag |
| 16 Jul 2026 | Transport Canada recall 2026345[2]<br>Issued for the model year · Visual system |
| 17 Sep 2026 | Transport Canada recall 2026442[2]<br>Issued for the model year · High voltage |
| 19 Oct 2026 | Listed for sale, Clarington, ON[5]<br>Auto Planet Durham · asking $43,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $43,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.