Register entry, as of 29 October 2026 Listed for sale Record ID 4d867e184caf

2019 Land Rover Range Rover Sport SE

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

SAL	WG2RK	5	K	A	874968
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jaguar Land Rover Limited	Range Rover Sport · 3.0 L	Computes	2019	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Diesel
Model	Range Rover Sport	Drive	AWD
Trim	SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2019

8 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

Visual system

2024289 23 May 2024

Issue: On certain Ranger Rover Sport models, the recall repairs completed by a Land Rover dealer during recall N778 (Transport Canada recall no. 2024-017) may not have been done correctly. As a result, a second repair is required. On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly. Note: This recall only affects vehicles equipped with a surround camera system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a new seal. The dealer will replace the rearview camera, if necessary.

Visual system

2024017 18 Jan 2024

For Ranger Rover Sport models, this recall was replaced by Transport Canada recall no. 2024-289. Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly. Note: This recall only affects vehicles equipped with a surround camera system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a new seal. The dealer will replace the rearview camera, if necessary.

Engine

2023189 30 Mar 2023

Issue: On certain vehicles, the water pump drive belt could become damaged and detach. As a result, the engine could overheat and cause the coolant elbow to rupture. If this happens, coolant could leak onto the turbocharger heatshield. Note: This recall only affects plug-in hybrid (PHEV) models. Safety Risk: A coolant leak onto the turbocharger heatshield may lead to a fire in the engine bay. Corrective Action: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealership to replace the engine coolant elbow and turbocharger feed coolant pipe.

2 more on the model-year record, cardog.app/tools/recalls/land-rover/range-rover-sport/2019

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $32,990[5], $4,995 under the median of $37,985[4].



Lowest ask	$22,900
Middle half	$33,995 – $41,999
Median ask	$37,985
This car	$32,990

Same model year · 25 live listings · as of 28 Oct 2026

OTHER 2019 LAND ROVER RANGE ROVER SPORT LISTINGS [5]

Mississauga, ON · 108,537 km	$41,999
Mississauga, ON · 82,349 km	$37,000
Leamington, ON · 82,349 km	$37,000
Leamington, ON · 108,537 km	$41,999
Essex, ON · 108,537 km	$41,999
Essex, ON · 82,349 km	$37,000

§4 EVENTS

2019	Model year 2019[1] Assembly plant Solihull, United Kingdom
17 Jan 2019	Transport Canada recall 2019029[2] Issued for the model year · Engine
25 Feb 2021	Transport Canada recall 2021102[2] Issued for the model year · Lights and instruments
30 Mar 2023	Transport Canada recall 2023189[2] Issued for the model year · Engine
18 Jan 2024	Transport Canada recall 2024017[2] Issued for the model year · Visual system
23 May 2024	Transport Canada recall 2024289[2] Issued for the model year · Visual system
10 Oct 2024	Transport Canada recall 2024599[2] Issued for the model year · Engine
17 Apr 2026	Transport Canada recall 2026196[2] Issued for the model year · High voltage
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
26 Oct 2026	Listed for sale, Richmond, BC[5] Signature Mazda · asking $32,990
29 Oct 2026	Listing last updated[5] asking $32,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 25 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.