Register entry, as of 27 October 2026 Listed for sale Record ID 9aaef3f869a3

# 2016 Land Rover Range Rover Sport HSE

3.0 L, 6 cylinders · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| SAL | WR2KF | 9 | G | A | 118123 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jaguar Land Rover Limited | Range Rover Sport · 3.0 L | Computes | 2016 | Solihull | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 3.0 L, 6 cylinders |
| Make | Land Rover | Fuel | Diesel |
| Model | Range Rover Sport | Drive | Not in the decode |
| Trim | HSE | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Solihull, England |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2016

**8** recalls listed by Transport Canada for this model year

### Suspension

2025274 22 May 2025

Issue: On certain vehicles, the front suspension knuckles could crack and/or break. A front knuckle that breaks while driving could cause a sudden loss of vehicle control. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front suspension knuckles. If the knuckles aren't cracked, the dealer will install retaining brackets. If cracks are found, the dealer will replace the knuckle(s).

### Structure

2025117 6 Mar 2025

Issue: On certain vehicles, the doors may not latch properly when they are closed. As a result, the doors could open while driving. Safety Risk: A door that opens suddenly while driving could create the risk of injury and/or increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the unilatch keyless vehicle (KV) software. The dealer will also inspect and, if necessary, replace the left-front and rear door latches.

### Seats and restraints

2022167 5 Apr 2022

Issue: A problem with the driver's seat belt could cause it not to lock-up as designed during braking or in a crash. Note: This recall replaces N333 (Transport Canada recall 2019-218). Vehicles that were inspected but that didn't have the driver's seat belt assembly replaced require a second inspection. Safety Risk: A seat belt that doesn't lock properly in a crash could cause an increased risk of injury. Corrective Actions: Jaguar Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver's seat belt assembly and replace it, as necessary.

### Steering

2019473 26 Sep 2019

Issue: On certain vehicles, the bolts that attach the electric power steering assist motor to the steering gear may corrode and break. This could cause a loss of power steering assist. This recall applies to vehicles originally sold or currently registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the aluminum bolts with steel ones and apply a wax sealer. If a bolt is found broken or breaks during the repair, a replacement steering rack will be installed.

### Seats and restraints

2019218 9 May 2019

Issue: A problem with the driver's seat belt could cause it not to lock-up as designed during braking or in a crash. Safety Risk: A seat belt that does not lock properly in a crash could cause an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the driver's seat belt assembly and replace it if necessary.

### Airbag

2017129 9 Mar 2017

Certain vehicles may have been equipped with a front passenger airbag that does not meet specifications. This could cause the front passenger airbag to fail to deploy properly in the event of a crash that warrants deployment of the passenger frontal airbag, which could increase the risk of injury to the occupants. Correction: Dealers will replace front passenger airbag module.

2 more on the model-year record, cardog.app/tools/recalls/land-rover/range-rover-sport/2016

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $28,600[5], $5,187 over the median of $23,413[4].




| | |
|---|---|
| Lowest ask | $15,000 |
| Middle half | $18,745 – $33,743 |
| Median ask | $23,413 |
| This car | $28,600 |

Same configuration · 14 live listings · as of 27 Oct 2026

### OTHER 2016 LAND ROVER RANGE ROVER SPORT LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 168,937 km | $15,000 |
| Windsor, ON · 168,937 km | $15,000 |
| London, ON · 168,937 km | $15,000 |
| New Westminster, BC · 96,040 km | $29,888 |
| Etobicoke, ON · 118,258 km | $25,400 |
| London, ON · 135,000 km | $34,991 |

## §4 EVENTS

2016 **Model year 2016**[1]
Assembly plant Solihull, England

| | |
|---|---|
| 22 Dec 2016 | Transport Canada recall 2016653[2]<br>Issued for the model year · Seats and restraints |
| 22 Dec 2016 | Transport Canada recall 2016652[2]<br>Issued for the model year · Airbag |
| 9 Mar 2017 | Transport Canada recall 2017129[2]<br>Issued for the model year · Airbag |
| 9 May 2019 | Transport Canada recall 2019218[2]<br>Issued for the model year · Seats and restraints |
| 26 Sep 2019 | Transport Canada recall 2019473[2]<br>Issued for the model year · Steering |
| 5 Apr 2022 | Transport Canada recall 2022167[2]<br>Issued for the model year · Seats and restraints |
| 6 Mar 2025 | Transport Canada recall 2025117[2]<br>Issued for the model year · Structure |
| 22 May 2025 | Transport Canada recall 2025274[2]<br>Issued for the model year · Suspension |
| 24 Oct 2026 | Listed for sale, New Westminster, BC[5]<br>Inline Motors · asking $28,600 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $28,600 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.