Register entry, as of 29 October 2026 Listed for sale Record ID cff045049313

2015 Toyota Yaris

1.5 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

VNK	KTUD3	8	F	A	047573
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Yaris · 1.5 L	Computes	2015	France	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Yaris	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, FRANCE, S.A.S.
Body	Hatchback	Plant	France

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/yaris/2015

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2019197 23 Apr 2019

Issue: Over time, the wiring to the side airbag sensors in the front doors could corrode. This could cause the front seat-mounted side airbags and curtain shield airbags not to work properly. Note: This problem would cause the airbag warning light (SRS warning) to turn on. Safety Risk: Airbags that do not work properly in a crash could create an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the front door wire harness assemblies, as necessary.

Suspension

2016256 25 May 2016

On certain vehicles, the front strut mount bearing components may be damaged when a high load is applied to the strut, such as when the vehicle is driven over a large bump. If the vehicle is operated with a damaged bearing, it could cause the upper strut rod assembly to separate, resulting in a loss of vehicle stability which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the strut mounting bearing with improved ones. If damage is found on the bearing, dealers will also replace the strut and front suspension support sub-assembly.

Suspension

2015070 17 Feb 2015

On certain vehicles, the rear axle hub bearing assembly bolt may not have been tightened properly. This could cause the bolts to become loose and detach from the hub assembly, which could damage the rear brake components. This could increase stopping distances and could also potentially cause wheel lock up, resulting in vehicle instability increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect bolts and tighten to specification. If bolts are missing, the rear axle hub bearing assembly and rear brake components will be replaced.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,495[5], $5,997 under the median of $13,492[4].

Lowest ask	$7,495
Middle half	$12,290 – $14,662
Median ask	$13,492
This car	$7,495

Same configuration · 12 live listings · as of 29 Oct 2026

OTHER 2015 TOYOTA YARIS LISTINGS [5]

Lévis,QC, QC · 140,586 km	$11,995
Montréal, QC · 130,177 km	$12,995
Lévis, QC · 140,586 km	$11,995
Lévis, QC · 140,586 km	$11,995
Scarborough, ON · 157,550 km	$12,388
Val-David, QC · 35,112 km	$13,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant France
17 Feb 2015	Transport Canada recall 2015070[2] Issued for the model year · Suspension
25 May 2016	Transport Canada recall 2016256[2] Issued for the model year · Suspension

23 Apr 2019	Transport Canada recall 2019197[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
5 May 2026	Listed for sale, Saint-Félicien, QC[5] Maison Mazda · asking $7,495
28 Oct 2026	Listing last updated[5] asking $7,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 12 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.