Register entry, as of 29 October 2026 Listed for sale Record ID be904c787dc4

# 2021 Mercedes-Benz Sprinter 907 (VS30)

2.2 L, 4 cylinders · 4x2 · Cargo Van · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| W1Y | 4DBHY | X | M | P | 373566 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz, Ag | Sprinter · 2.2 L | Computes | 2021 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.2 L, 4 cylinders |
| Make | Mercedes-Benz | Fuel | Diesel |
| Model | Sprinter | Drive | 4x2 |
| Trim | 907 (VS30) | Maker | MERCEDES-BENZ, AG |
| Body | Cargo Van | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2021

**11** recalls listed by Transport Canada for this model year

### Structure — 2023689 — 21 Dec 2023

Issue: On certain vehicles, the rear frame may be missing reinforcements. As a result, the frame could become damaged and cause a change vehicle stability. This problem could also cause the mounting points for the third-row seats to fail in a crash. Safety Risk: A change in vehicle stability could cause a loss of control and increase the risk of a crash. Additionally, a seat that moves or separates in a crash could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the longitudinal frame members.

### Fuel system — 2023353 — 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Lights and instruments — 2023167 — 24 Mar 2023

Issue: On certain vehicles, a software problem could cause the instrument cluster not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, indicator lamps, and warning messages. In addition, the warning sounds may not work. Safety Risk: Warnings and malfunction tell-tale information that does not display could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the instrument cluster software.

### Powertrain
2022602 21 Oct 2022

Issue: In certain conditions, the vehicle could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set. Note: You should always follow the parking procedure in the owner's manual, and set the parking brake each time that you park. Safety Risk: A parked vehicle that rolls away could create a risk of a crash or an injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the software of various control units.

### Visual system
2022214 27 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

### Label
2022061 10 Feb 2022

Issue: The tire and loading information label on certain vehicles may list the wrong combined weight of occupants and cargo. As a result, you could overload the vehicle. This could cause excessive tire wear and lead to a tire failure. Safety Risk: A tire failure could cause a loss of control and result in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the tire and loading information label. Additionally, the dealer will inspect the tires for excessive wear due to this issue, and replace them if necessary.

5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/sprinter/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

United States: 18 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $29,999[5], $4,890 under the median of $34,889[4].




| | |
|---|---|
| Lowest ask | $23,995 |
| Middle half | $29,624 – $37,582 |
| Median ask | $34,889 |
| This car | $29,999 |

Same configuration · 12 live listings · as of 29 Oct 2026

OTHER 2021 MERCEDES-BENZ SPRINTER LISTINGS [5]

| | |
|---|---|
| Saint-Sulpice, QC · 118,811 km | $36,995 |
| Boisbriand, QC · 103,000 km | $35,995 |
| Ste-Marie de Beauce, QC · 37,392 km | $54,900 |
| Toronto, ON · 178,049 km | $46,999 |
| Toronto, ON · 289,833 km | $28,999 |
| Surrey, BC · 108,375 km | $38,999 |

## §4 EVENTS

2021 Model year 2021[1]
Assembly plant Germany

| | |
|---|---|
| 13 Apr 2021 | Transport Canada recall 2021221[2]<br>Issued for the model year · Lights and instruments |
| 4 Jun 2021 | Transport Canada recall 2021349[2]<br>Issued for the model year · Visual system |
| 6 Aug 2021 | Transport Canada recall 2021494[2]<br>Issued for the model year · Seats and restraints |
| 7 Oct 2021 | Transport Canada recall 2021620[2]<br>Issued for the model year · Electrical |
| 16 Dec 2021 | Transport Canada recall 2021765[2]<br>Issued for the model year · Powertrain |
| 10 Feb 2022 | Transport Canada recall 2022061[2]<br>Issued for the model year · Label |
| 27 Apr 2022 | Transport Canada recall 2022214[2]<br>Issued for the model year · Visual system |
| 21 Oct 2022 | Transport Canada recall 2022602[2]<br>Issued for the model year · Powertrain |
| 24 Mar 2023 | Transport Canada recall 2023167[2]<br>Issued for the model year · Lights and instruments |
| 23 Jun 2023 | Transport Canada recall 2023353[2]<br>Issued for the model year · Fuel system |
| 21 Dec 2023 | Transport Canada recall 2023689[2]<br>Issued for the model year · Structure |
| 27 Oct 2026 | Listed for sale, Toronto, ON[5]<br>Smart Cars Sales · asking $29,999 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $29,999 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.