Register entry, as of 28 October 2026 Listed for sale Record ID 04f6c90eb11d

# 2020 Audi Q5 quattro Prestige

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WA1 | CNAFY | 7 | L | 2 | 082913 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Audi Ag | Q5 · 2.0 L | Computes | 2020 | San Jose Chiapa | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.0 L, 4 cylinders |
| Make | Audi | Fuel | Gasoline |
| Model | Q5 | Drive | AWD |
| Trim | quattro Prestige | Maker | AUDI AG |
| Body | Sport Utility Vehicle | Plant | San Jose Chiapa, Chiapas, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q5/2020

**5** recalls listed by Transport Canada for this model year

### Accessories

2023659 13 Dec 2023

Issue: Under certain conditions, the plug for the 220 V compact vehicle charging cable could become damaged by the house power outlet. As a result, the cable could overheat while charging. Note: This recall only affects electric and plug-in hybrid electric (PHEV) models. Safety Risk: Wiring that overheats could create a fire risk. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to replace the vehicle charging cable. For unsold vehicles, the dealer will remove the charging cable before they are delivered to consumers.

### Electrical

2021740 9 Dec 2021

Issue: On certain vehicles, if you spill liquid on the rear seat, or drive through heavy rain or deep water, the gateway control module could be damaged. If this happens, the vehicle may enter emergency mode and suddenly lose power to the wheels. Note: The power steering and braking systems will continue to work. You may also see warning messages on the instrument panel when this happens. Safety Risk: A sudden loss of power to the wheels may increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to install a protective cover on the gateway control module and seal an underbody seam, as necessary.

### Suspension

2021249 26 Apr 2021

Issue: On certain vehicles, the lock nuts for the rear trailing arm bolts may be defective. If a nut breaks, there could be sudden changes in rear wheel alignment. This can cause a loss of vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear trailing arm lock nuts. If necessary, the associated bolt(s) will be replaced as well.

### Seats and restraints

2020392 26 Aug 2020

Issue: On certain vehicles, parts of the front seat frame and backrest adjuster may not have been properly welded. As a result, the backrest adjustment could break in a rear-end crash and allow to seat to move. Safety Risk: A seatback that fails could cause an increased risk of injury in a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver and passenger front seats. The seatback frames will be replaced, as necessary.

### Structure

2019520 16 Oct 2019

Issue: On certain vehicles, the cover trim for the rear wheel arches may become loose. This could cause the trim to detach while driving. Safety Risk: Trim that completely detaches from the vehicle could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the four clips that secure the forward part of the rear wheel arch trims.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $27,689[5], $4,691 over the median of $22,998[4].




| | |
|---|---|
| Lowest ask | $17,890 |
| Middle half | $21,800 – $26,500 |
| Median ask | $22,998 |
| This car | $27,689 |

Same model year · 37 live listings · as of 28 Oct 2026

#### OTHER 2020 AUDI Q5 LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 144,427 km | $20,987 |
| Thornhill, ON · 83,321 km | $25,598 |
| Waterloo, ON · 133,000 km | $21,995 |
| Vancouver, BC · 48,500 km | $31,900 |
| London, ON · 110,700 km | $25,495 |
| Calgary, AB · 102,583 km | $24,993 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant San Jose Chiapa, Chiapas, Mexico |
| 16 Oct 2019 | Transport Canada recall 2019520[2]<br>Issued for the model year · Structure |
| 26 Aug 2020 | Transport Canada recall 2020392[2]<br>Issued for the model year · Seats and restraints |
| 26 Apr 2021 | Transport Canada recall 2021249[2]<br>Issued for the model year · Suspension |

| | |
|---|---|
| 9 Dec 2021 | Transport Canada recall 2021740[2]<br>Issued for the model year · Electrical |
| 13 Dec 2023 | Transport Canada recall 2023659[2]<br>Issued for the model year · Accessories |
| 28 Oct 2026 | Listed for sale, Halifax, NS[5]<br>O&s;Regan&s;s Volkswagen Halifax · asking $27,689 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 37 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.