Register entry, as of 29 October 2026 Listed for sale Record ID 96a6e2b98c53

# 2023 Audi Q5 S line quattro Prestige

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WA1 | FAAFY | 8 | P | 2 | 183604 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Audi Ag | Q5 · 2.0 L | Computes | 2023 | San José Chiapa | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.0 L, 4 cylinders |
| Make | Audi | Fuel | Gasoline |
| Model | Q5 | Drive | AWD |
| Trim | S line quattro Prestige | Maker | AUDI AG |
| Body | Sport Utility Vehicle | Plant | San José Chiapa, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q5/2023

**7** recalls listed by Transport Canada for this model year

### High voltage

2025369 10 Jul 2025

Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. This recall replaces Transport Canada recall no. 2025-064. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

### Engine

2025244 7 May 2025

Issue: On certain vehicles, the screws for the cylinder head cover could loosen and cause an oil leak. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace and tighten the cylinder head cover screws.

### High voltage

2025064 12 Feb 2025

This recall was replaced by Transport Canada recall no. 2025-369. Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. This recall replaces Transport Canada recall no. 2024-723. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

### High voltage

2024723 27 Nov 2024

This recall was replaced by Transport Canada recall no. 2025-064. Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

### Airbag

2024209 3 Apr 2024

Issue: On certain vehicles, the passenger occupant detection system may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a yellow airbag warning light to turn on in the instrument panel. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger seat occupant detection system control module.

### Accessories

2023659 13 Dec 2023

Issue: Under certain conditions, the plug for the 220 V compact vehicle charging cable could become damaged by the house power outlet. As a result, the cable could overheat while charging. Note: This recall only affects electric and plug-in hybrid electric (PHEV) models. Safety Risk: Wiring that overheats could create a fire risk. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to replace the vehicle charging cable. For unsold vehicles, the dealer will remove the charging cable before they are delivered to consumers.

1 more on the model-year record, cardog.app/tools/recalls/audi/q5/2023

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $39,188[5], $350 over the median of $38,838[4].

| | |
|---|---|
| Lowest ask | $32,875 |
| Middle half | $36,621 – $40,455 |
| Median ask | $38,838 |
| This car | $39,188 |

Same configuration · 22 live listings · as of 29 Oct 2026

### OTHER 2023 AUDI Q5 LISTINGS [5]

| | |
|---|---|
| Orangeville, ON · 60,289 km | $35,572 |
| Sherwood Park, AB · 60,610 km | $40,507 |
| Sherwood Park, AB · 63,980 km | $40,507 |
| Sherwood Park, AB · 73,014 km | $39,907 |
| Brossard, QC · 28,612 km | $30,998 |
| Brossard, QC · 75,818 km | $30,678 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant San José Chiapa, Mexico |
| 7 Oct 2022 | Transport Canada recall 2022576[2]<br>Issued for the model year · Engine |
| 13 Dec 2023 | Transport Canada recall 2023659[2]<br>Issued for the model year · Accessories |
| 3 Apr 2024 | Transport Canada recall 2024209[2]<br>Issued for the model year · Airbag |
| 27 Nov 2024 | Transport Canada recall 2024723[2]<br>Issued for the model year · High voltage |
| 12 Feb 2025 | Transport Canada recall 2025064[2]<br>Issued for the model year · High voltage |
| 7 May 2025 | Transport Canada recall 2025244[2]<br>Issued for the model year · Engine |
| 10 Jul 2025 | Transport Canada recall 2025369[2]<br>Issued for the model year · High voltage |
| 16 Sep 2026 | Listed for sale, Orillia, ON[5]<br>ORILLIA VOLKSWAGEN · asking $39,188 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $39,188 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 22 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.