Register entry, as of 29 October 2026 Listed for sale Record ID 0884d60cd428

2019 Mercedes-Benz Sprinter

3.0 L, 6 cylinders · 4x2 · Cargo Van · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

WD3	BF1CD	4	K	P	109822
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz, Ag	Sprinter · 3.0 L	Computes	2019	Germany	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Diesel
Model	Sprinter	Drive	4x2
Trim	Not in the decode	Maker	MERCEDES-BENZ, AG
Body	Cargo Van	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2019

31 recalls listed by Transport Canada for this model year

Structure — 2023689 — 21 Dec 2023

Issue: On certain vehicles, the rear frame may be missing reinforcements. As a result, the frame could become damaged and cause a change vehicle stability. This problem could also cause the mounting points for the third-row seats to fail in a crash. Safety Risk: A change in vehicle stability could cause a loss of control and increase the risk of a crash. Additionally, a seat that moves or separates in a crash could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the longitudinal frame members.

Lights and instruments — 2023167 — 24 Mar 2023

Issue: On certain vehicles, a software problem could cause the instrument cluster not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, indicator lamps, and warning messages. In addition, the warning sounds may not work. Safety Risk: Warnings and malfunction tell-tale information that does not display could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the instrument cluster software.

Electrical — 2023080 — 17 Feb 2023

Issue: In certain conditions, the connection between the between fuse and fuse mount for the blower motor could overheat. Safety Risk: A fuse and wiring that overheats could create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to replace and relocate the blower motor fuse and its wiring. To reduce the safety risk, Mercedes-Benz recommends that you should only operate the blower in manual mode, and not use either the highest or lowest temperature settings until the recall repairs have been completed.

Powertrain

2022602 21 Oct 2022

Issue: In certain conditions, the vehicle could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set. Note: You should always follow the parking procedure in the owner's manual, and set the parking brake each time that you park. Safety Risk: A parked vehicle that rolls away could create a risk of a crash or an injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the software of various control units.

Visual system

2022214 27 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

Powertrain

2021765 16 Dec 2021

Issue: In certain conditions, the vehicle could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set. Note: You should always follow the parking procedure in the owner's manual, and set the parking brake each time that you park. Safety Risk: A parked vehicle that rolls away could create a risk of a crash or an injury. Corrective Actions: Mercedes-Benz will notify owners by mail. The corrective actions for this recall are under development. Once a recall repair is available, Mercedes-Benz will send you a second notice and advise you to take your vehicle to a dealer to update the electronic stability program (ESP) control unit.

25 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/sprinter/2019

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

United States: 42 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $33,988[5], $3,003 over the median of $30,985[4].



Lowest ask	$17,888
Middle half	$27,999 – $43,950
Median ask	$30,985
This car	$33,988

Same model year · 17 live listings · as of 29 Oct 2026

OTHER 2019 MERCEDES-BENZ SPRINTER LISTINGS [5]

Toronto, ON · 421,610 km	$17,888
Mirabel, QC · 93,420 km	$29,995
Saint-Sulpice, QC · 180,234 km	$29,995
Acton Vale, QC · 22,850 km	$43,950
Fenwick, ON · 222,000 km	$25,890
Kitchener, ON · 90,000 km	$27,999

§4 EVENTS

2019	Model year 2019[1] Assembly plant Germany
19 Mar 2019	Transport Canada recall 2019146[2] Issued for the model year · Lights and instruments
11 Apr 2019	Transport Canada recall 2019181[2] Issued for the model year · Lights and instruments
18 Apr 2019	Transport Canada recall 2019189[2] Issued for the model year · Lights and instruments
3 Jul 2019	Transport Canada recall 2019333[2] Issued for the model year · Visual system
16 Aug 2019	Transport Canada recall 2019414[2] Issued for the model year · Lights and instruments
23 Sep 2019	Transport Canada recall 2019467[2] Issued for the model year · Structure
8 Nov 2019	Transport Canada recall 2019563[2] Issued for the model year · Fuel system
13 Feb 2020	Transport Canada recall 2020059[2] Issued for the model year · Engine
13 Feb 2020	Transport Canada recall 2020058[2] Issued for the model year · Engine
26 Feb 2020	Transport Canada recall 2020077[2] Issued for the model year · Structure
26 Feb 2020	Transport Canada recall 2020076[2] Issued for the model year · Steering
31 Mar 2020	Transport Canada recall 2020135[2] Issued for the model year · Other
31 Mar 2020	Transport Canada recall 2020134[2] Issued for the model year · Brakes
4 Jun 2020	Transport Canada recall 2020248[2] Issued for the model year · Airbag
29 Jul 2020	Transport Canada recall 2020349[2] Issued for the model year · Suspension
1 Oct 2020	Transport Canada recall 2020465[2] Issued for the model year · Fuel system
29 Oct 2020	Transport Canada recall 2020517[2] Issued for the model year · Steering

13 Nov 2020	Transport Canada recall 2020545[2] Issued for the model year · Electrical
22 Dec 2020	Transport Canada recall 2020641[2] Issued for the model year · Brakes
19 Feb 2021	Transport Canada recall 2021076[2] Issued for the model year · Visual system
15 Mar 2021	Transport Canada recall 2021149[2] Issued for the model year · Brakes
9 Apr 2021	Transport Canada recall 2021216[2] Issued for the model year · Steering
13 Apr 2021	Transport Canada recall 2021221[2] Issued for the model year · Lights and instruments
4 Jun 2021	Transport Canada recall 2021349[2] Issued for the model year · Visual system
8 Jun 2021	Transport Canada recall 2021356[2] Issued for the model year · Electrical
16 Dec 2021	Transport Canada recall 2021765[2] Issued for the model year · Powertrain
27 Apr 2022	Transport Canada recall 2022214[2] Issued for the model year · Visual system
21 Oct 2022	Transport Canada recall 2022602[2] Issued for the model year · Powertrain
17 Feb 2023	Transport Canada recall 2023080[2] Issued for the model year · Electrical
24 Mar 2023	Transport Canada recall 2023167[2] Issued for the model year · Lights and instruments
21 Dec 2023	Transport Canada recall 2023689[2] Issued for the model year · Structure
24 Oct 2026	Listed for sale, Toronto, ON[5] ELEGANT AUTO SALES INC. · asking $33,988

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 17 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.