Register entry, as of 29 October 2026 Listed for sale Record ID 85695efa1667

2008 Mercedes-Benz E-Class E350 4-MATIC

3.5 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDB	UF87X	X	8	B	315873
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	E-Class · 3.5 L	Computes	2008	Germany	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.5 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	E-Class	Drive	AWD
Trim	E350 4-MATIC	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/e-class/2008

4 recalls listed by Transport Canada for this model year

Structure — 2022740 — 22 Dec 2022

Issue: On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: Vehicles that were inspected under Transport Canada recalls 2019-668 and 2021-478 also require this inspection. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.

Structure — 2021478 — 23 Jul 2021

Issue: This recall is for certain vehicles inspected under Mercedes-Benz recall 7891003 (Transport Canada recall 2019-668) that require a second inspection. On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: This recall affects 2006 and 2007 models originally equipped with a sunroof. Additionally, some 2001-2011 models may have had an affected sunroof installed during a repair. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.

Structure

2019668 23 Dec 2019

Issue: On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: This recall affects 2006 and 2007 models originally equipped with a sunroof. Additionally, some 2001-2011 models may have had an affected sunroof installed during a repair. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.

Suspension

2012176 11 Jun 2012

On certain E-Class Wagons, the load levelling rear suspension could malfunction. This could trigger a continuous attempt to increase the pressure in the air bellows, which can lead to uncomfortable and stiff suspension characteristics. Ultimately, this could cause a loss of air pressure in the bellows, which could result in poor vehicle handling characteristics, increasing the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the level control system connecting rod with an updated version.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $8,999[4], $174 over the median of $8,825[3].

Lowest ask	$3,999
Middle half	$7,525 – $8,962
Median ask	$8,825
This car	$8,999

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2008 MERCEDES-BENZ E-CLASS LISTINGS [4]

Surrey, BC · 168,579 km	$8,950
Calgary, AB · 143,187 km	$8,700
Rodney, ON · 214,232 km	$3,999

§4 EVENTS

2008	Model year 2008[1] Assembly plant Germany
11 Jun 2012	Transport Canada recall 2012176[2] Issued for the model year · Suspension
23 Dec 2019	Transport Canada recall 2019668[2] Issued for the model year · Structure
23 Jul 2021	Transport Canada recall 2021478[2] Issued for the model year · Structure
22 Dec 2022	Transport Canada recall 2022740[2] Issued for the model year · Structure

25 Oct 2025	Listed for sale, Rodney, ON[4] Rymon Auto Sales · asking $8,999
29 Oct 2026	Listing last updated[4] asking $8,999

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.