Register entry, as of 28 October 2026 Listed for sale Record ID 8aa8878dfff0

2015 Mercedes-Benz B-Class B250

2.0 L, 4 cylinders · AWD · Hatchback

VEHICLE IDENTIFICATION NUMBER [1]

WDD	MH4GB	2	F	J	349467
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	B-Class · 2.0 L	Computes	2015	Germany	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Not in the decode
Model	B-Class	Drive	AWD
Trim	B250	Maker	Mercedes-Benz Cars
Body	Hatchback	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/b-class/2015

7 recalls listed by Transport Canada for this model year

Steering

2021507 11 Aug 2021

Issue: On certain vehicles, the power steering control unit may corrode. If this happens, moisture could enter the control unit and cause it to fail. This could cause a loss of power steering assist. Note: This is an expansion of Mercedes-Benz recall 4694202 (Transport Canada Recall No. 2020-617). This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist would result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the power steering control unit.

Steering

2020617 14 Dec 2020

Issue: On certain vehicles, the power steering control unit may corrode. If this happens, moisture could enter the control unit and cause it to fail. This could cause a loss of power steering assist. Note: This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist would result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the power steering control unit.

Airbag

2019632 13 Dec 2019

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly. In some cases, this could cause the airbag system to turn off the passenger-front airbag, even if an adult is seated in the front passenger seat. Alternatively, the airbag may not be turned off when a child seat is installed in the front passenger seat. Safety Risk: An airbag that deploys in front of a child seat, or an airbag that doesn't properly deploy in front of a passenger could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion.

Airbag

2017490 10 Oct 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.

Engine

2017062 9 Feb 2017

On certain vehicles, the starting current limiter could be overloaded under certain conditions. In the event the starter is blocked, a very high electric current could flow through the starting current limiter during repeated engine starting attempts. The high electric draw could cause the starting current limiter to overheat causing the surrounding components to melt which would increase the risk of fire causing injury and/or damage to property. Correction : Dealers will install an additional fuse in the electrical line to the starter.

Seats and restraints

2016157 13 Apr 2016

On certain vehicles equipped with the Easy-Vario rear seat option, the rear screws used to bolt the rear seat to the body of the vehicle may be missing on one side. In the event of a crash, the rear seats may lift up from the body and the seat belt anchoring may not function as designed which could increase the risk of injury. Correction : Dealers will inspect and repair the rear seats as necessary.

1 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/b-class/2015

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $8,995[4], $3,870 under the median of $12,865[3].

Lowest ask	$8,995
Middle half	$10,698 – $12,982
Median ask	$12,865
This car	$8,995

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2015 MERCEDES-BENZ B-CLASS LISTINGS [4]

Oakville, ON · 122,184 km	$9,998
Calgary, AB · 149,000 km	$13,999
Richmond, BC · 117,361 km	$12,800
Cambridge, ON · 146,377 km	$12,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant Germany
13 Oct 2015	Transport Canada recall 2015463[2] Issued for the model year · Engine

13 Apr 2016	Transport Canada recall 2016157[2] Issued for the model year · Seats and restraints
9 Feb 2017	Transport Canada recall 2017062[2] Issued for the model year · Engine
10 Oct 2017	Transport Canada recall 2017490[2] Issued for the model year · Airbag
13 Dec 2019	Transport Canada recall 2019632[2] Issued for the model year · Airbag
14 Dec 2020	Transport Canada recall 2020617[2] Issued for the model year · Steering
11 Aug 2021	Transport Canada recall 2021507[2] Issued for the model year · Steering
25 Oct 2026	Listed for sale, Komoka, ON[4] Cars in Lobo · asking $8,995
28 Oct 2026	Listing last updated[4] asking $8,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.