Register entry, as of 27 October 2026 Listed for sale Record ID 61168e87b581

2011 MINI Clubman

1.6 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMW	ZF3C5	6	B	T	Y00931
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
MINI · BMW AG	Clubman · 1.6 L	Computes	2011	Oxford	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	1.6 L, 4 cylinders
Make	MINI	Fuel	Gasoline
Model	Clubman	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Hatchback	Plant	Oxford, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mini/clubman/2011

3 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Electrical

2023281 11 May 2023

Issue: On certain vehicles, the footwell module (FRM) may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: BMW will notify owners by mail. The corrective actions for this recall are under development. BMW advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Electrical

2018544 3 Oct 2018

On certain vehicles, the footwell module (FRM3) may become contaminated by a mixture of salt and moisture which could lead to corrosion over time. This could cause a short circuit, resulting in overheating of the module that could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect the footwell module, and replace if necessary. A protective film will be also installed over the module. Note: Owners are advised to park the vehicle outdoors until the recall repairs have been completed.

Listed for the model year, not checked against your VIN. MINI confirms which apply.
Check your VIN with MINI Canada or call a MINI dealer with your VIN.
crm.bmw.ca/en-CA/VehicleRecall

§3 VALUE [3]

This car asks $4,888[4], the median[3].



Lowest ask	$4,888
Middle half	$4,888 – $4,888
Median ask	$4,888
This car	$4,888

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2011	Model year 2011[1] Assembly plant Oxford, United Kingdom
3 Oct 2018	Transport Canada recall 2018544[2] Issued for the model year · Electrical
11 May 2023	Transport Canada recall 2023281[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
23 May 2026	Listed for sale, North York, ON[4] Exclusive Fine Cars · asking $4,888
27 Oct 2026	Listing last updated[4] asking $4,888

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026
[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.