Register entry, as of 27 October 2026 Listed for sale Record ID 4c9267d10811

2010 Porsche Panamera

4.8 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	AB2A7	6	A	L	065506
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Panamera · 4.8 L	Computes	2010	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	4.8 L, 8 cylinders
Make	Porsche	Fuel	Gasoline
Model	Panamera	Drive	Not in the decode
Trim	Not in the decode	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sedan	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/panamera/2010

4 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Powertrain

2019290 12 Jun 2019

Issue: On certain vehicles, the transmission shifter could detach from the transmission. This could cause the transmission not to shift gears when the shifter is moved. As a result, the transmission could be in a different gear than the gear shifter indicates. If a driver attempts to exit the vehicle while the transmission is not in Park, and the parking brake is not applied, the vehicle could move suddenly. Safety Risk: Sudden and unexpected movement of the vehicle could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct them to take their vehicle to a dealer to replace the shifter cable bushing. Owners are reminded to use the parking brake anytime the vehicle is parked.

Engine

2017296 7 Jun 2017

On certain vehicles, the fasteners of the camshaft adjusters could fail due to an assembly problem. If this occurs, this could cause abnormal engine noises, vibrations, illumination of the check engine light and could cause the vehicle to stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the fastening screws of the camshaft adjusters and if necessary, replace the camshaft adjuster assemblies.

Seats and restraints

2010107 7 Apr 2010

On certain vehicles, if the front seats are adjusted towards an extreme position, it is possible that the function of the locking mechanism of the seatbelt mount would no longer be guaranteed. The seatbelt mount could detach from the anchoring system when the seatbelt is fastened or opened. This situation, in the event of a crash, could result in personal injury or death. Correction: Dealers will install an additional locking element on the seatbelt anchoring system.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,888[5], $1,512 under the median of $22,400[4].

Lowest ask	$20,888
Middle half	$21,647 – $22,924
Median ask	$22,400
This car	$20,888

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2010 PORSCHE PANAMERA LISTINGS [5]

North York, ON · 136,000 km	$22,900
Vaughan, ON · 94,048 km	$21,900
Calgary, AB · 143,367 km	$22,995

§4 EVENTS

2010	Model year 2010[1] Assembly plant Leipzig, Germany
7 Apr 2010	Transport Canada recall 2010107[2] Issued for the model year · Seats and restraints
7 Jun 2017	Transport Canada recall 2017296[2] Issued for the model year · Engine
12 Jun 2019	Transport Canada recall 2019290[2] Issued for the model year · Powertrain
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
1 Oct 2026	Listed for sale, Etobicoke, ON[5] Bespoke Auto Gallery · asking $20,888
26 Oct 2026	Listing last updated[5] asking $20,888

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.