Register entry, as of 28 October 2026 Listed for sale Record ID c83dad922326

2015 Porsche Boxster S

3.4 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	CB2A8	1	F	S	140532
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Boxster · 3.4 L	Computes	2015	Stuttgart-Zuffenhausen	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.4 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Boxster	Drive	Not in the decode
Trim	S	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Convertible	Plant	Stuttgart-Zuffenhausen, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/boxster/2015

3 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Suspension

2021539 1 Sep 2021

Issue: On certain vehicles, the rear axle carrier side mounts may crack and eventually break. If both mounts break while driving, there could be a sudden loss of vehicle control. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear axle carrier side sections.

Structure

2014498 3 Nov 2014

On certain vehicles the front hood lock may have been improperly manufactured. The front hood lock upper components, on which the catch bar are riveted to the mounting plate, were not produced according to specifications. This could result in the hood opening unexpectedly while the vehicle is being driven. This could compromise the driver's ability to see the road and its users, as well as cause damage to the windshield, which could result in a crash causing injury and/or property damage. Correction: Dealers will replace the upper part of the lock on the front hood.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $63,900[5], $1,000 over the median of $62,900[4].



Lowest ask	$61,900
Middle half	$62,400 – $63,400
Median ask	$62,900
This car	$63,900

Same model year · 2 live listings · as of 28 Oct 2026

§4 EVENTS

2015	Model year 2015[1] Assembly plant Stuttgart-Zuffenhausen, Germany
3 Nov 2014	Transport Canada recall 2014498[2] Issued for the model year · Structure
1 Sep 2021	Transport Canada recall 2021539[2] Issued for the model year · Suspension
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
16 Oct 2026	Listed for sale, Ste-Marie, QC[5] ED Autos · asking $63,900
28 Oct 2026	Listing last updated[5] asking $63,900

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.