Register entry, as of 29 October 2026 Listed for sale Record ID 2b1ca85a3a45

2011 Porsche Cayenne

4.8 L, 8 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP1	AB2A2	4	B	L	A54198
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Cayenne · 4.8 L	Computes	2011	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	4.8 L, 8 cylinders
Make	Porsche	Fuel	Gasoline
Model	Cayenne	Drive	Not in the decode
Trim	Not in the decode	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sport Utility Vehicle	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/cayenne/2011

6 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Label

2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

Engine

2017296 7 Jun 2017

On certain vehicles, the fasteners of the camshaft adjusters could fail due to an assembly problem. If this occurs, this could cause abnormal engine noises, vibrations, illumination of the check engine light and could cause the vehicle to stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the fastening screws of the camshaft adjusters and if necessary, replace the camshaft adjuster assemblies.

Brakes

2016131 23 Mar 2016

On certain vehicles, a circlip at the brake pedal hinge may not have been installed at the time of assembly. This could allow the pivot pin to move out of position, which would allow the pedal to wobble, and could fracture the brake pedal pivot through continued use. A fractured hinge would allow the pedal to separate from its pivot, which could lead to impaired brake function and increase stopping distances, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and add a circlip as necessary.

Fuel system

2015016 16 Jan 2015

On certain vehicles, the fuel rail may leak fuel in the engine compartment under certain driving conditions. Leaking fuel in the presence of an ignition source could lead to a fire causing injury and/or damage to property. Correction: Dealers will replace the fuel rail and corresponding seals.

Lights and instruments

2012070 22 Feb 2012

On certain vehicles, the headlamp assemblies may not have been secured correctly during vehicle assembly. As a result, the headlamps could loosen and detach from the vehicle, which could compromise the driver's ability to see the road and its users. In addition, the errant headlamp module could strike a vehicle, a stationary object, or a bystander. These issues could result in property damage and/or personal injury. Correction: Dealers will replace the headlamp locking components.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,900[5], $1,050 over the median of $13,850[4].

Lowest ask	$7,995
Middle half	$11,599 – $14,924
Median ask	$13,850
This car	$14,900

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2011 PORSCHE CAYENNE LISTINGS [5]

Edmonton, AB · 177,123 km	$12,800
Regina, SK · 335,000 km	$7,995
Richmond, BC · 171,716 km	$14,995

§4 EVENTS

2011	Model year 2011[1] Assembly plant Leipzig, Germany
22 Feb 2012	Transport Canada recall 2012070[2] Issued for the model year · Lights and instruments
16 Jan 2015	Transport Canada recall 2015016[2] Issued for the model year · Fuel system

23 Mar 2016	Transport Canada recall 2016131[2] Issued for the model year · Brakes
7 Jun 2017	Transport Canada recall 2017296[2] Issued for the model year · Engine
18 Apr 2019	Transport Canada recall 2019192[2] Issued for the model year · Label
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
15 Jun 2026	Listed for sale, Toronto, ON[5] World Fine Cars · asking $14,900
28 Oct 2026	Listing last updated[5] asking $14,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.