Register entry, as of 28 October 2026 Listed for sale Record ID 43ff9c30bab9

# 2016 Porsche Macan

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
|---|---|---|---|---|---|
| WP1 | AB2A5 | 9 | G | L | B50412 |
| Dr. Ing. H.C.F. Porsche Ag | Macan · 3.0 L | Computes | 2016 | Leipzig | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 3.0 L, 6 cylinders |
| Make | Porsche | Fuel | Gasoline |
| Model | Macan | Drive | Not in the decode |
| Trim | Not in the decode | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Sport Utility Vehicle | Plant | Leipzig, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2016

**7** recalls listed by Transport Canada for this model year

### Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

### Airbag

2021113 4 Mar 2021

Issue: On certain vehicles, the front passenger seat occupant sensor mat could stop working over time. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: The airbag warning light or passenger airbag OFF light will turn on if the sensor mat stops working. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion and occupant sensor mat.

### Fuel system

2020054 13 Feb 2020

Issue: Over time, small cracks could develop in the fuel pump outlet. If this happens, there could be a fuel odour or fuel leak under the rear seat area. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump service cover. The fuel filter flanges will be inspected, and replaced if any cracks are found.

### Label
2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

### Fuel system
2017241 3 May 2017

On certain vehicles, fine hairline cracks could appear after an extended period of use on the filter flange of the fuel pump. A fuel leak in the presence of an ignition source could cause a fire, increase the risk of injury and/or damage to property. Correction: Dealers will inspect and replace the fuel filter flange if cracks are found. If no cracks are found, a film will be affixed to the filter flange to protect it.

### Airbag
2017107 1 Mar 2017

On certain vehicles, the front passenger seat occupancy detection mat conductive fabric may fracture over time. As a result, the passenger airbag could deactivate, illuminating the passenger airbag OFF lamp. Failure of the passenger airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the occupant seat occupancy detection mat with a new improved mat.

1 more on the model-year record, cardog.app/tools/recalls/porsche/macan/2016

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $22,500[5], $1,056 over the median of $21,444[4].

| | |
|---|---|
| Lowest ask | $17,800 |
| Middle half | $19,496 – $22,592 |
| Median ask | $21,444 |
| This car | $22,500 |

Same configuration · 8 live listings · as of 28 Oct 2026

### OTHER 2016 PORSCHE MACAN LISTINGS [5]

| | |
|---|---|
| Surrey, BC · 104,000 km | $22,869 |
| Ottawa, ON · 143,211 km | $20,900 |
| Toronto, ON · 0 km | $17,988 |
| Toronto, ON · 0 km | $21,988 |
| Richmond, BC · 72,510 km | $28,500 |
| North Vancouver District, BC · 121,557 km | $19,999 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Leipzig, Germany |
| 29 Oct 2015 | Transport Canada recall 2015514[2]<br>Issued for the model year · Fuel system |

| | |
|---|---|
| 1 Mar 2017 | Transport Canada recall 2017107[2]<br>Issued for the model year · Airbag |
| 3 May 2017 | Transport Canada recall 2017241[2]<br>Issued for the model year · Fuel system |
| 18 Apr 2019 | Transport Canada recall 2019192[2]<br>Issued for the model year · Label |
| 13 Feb 2020 | Transport Canada recall 2020054[2]<br>Issued for the model year · Fuel system |
| 4 Mar 2021 | Transport Canada recall 2021113[2]<br>Issued for the model year · Airbag |
| 31 Aug 2022 | Transport Canada recall 2022487[2]<br>Issued for the model year · Lights and instruments |
| 26 Oct 2026 | Listed for sale, Brampton, ON[5]<br>Northwest Lexus · asking $22,500 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $22,500 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.