Register entry, as of 28 October 2026 Listed for sale Record ID dd96561b846b

# 2018 Porsche Macan Macan GTS

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WP1 | AG2A5 | X | J | L | B63999 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dr. Ing. H.C.F. Porsche Ag | Macan · 3.0 L | Computes | 2018 | Leipzig | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 3.0 L, 6 cylinders |
| Make | Porsche | Fuel | Gasoline |
| Model | Macan | Drive | AWD |
| Trim | Macan GTS | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Sport Utility Vehicle | Plant | Leipzig, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2018

**5** recalls listed by Transport Canada for this model year

### Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

### Airbag

2021113 4 Mar 2021

Issue: On certain vehicles, the front passenger seat occupant sensor mat could stop working over time. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: The airbag warning light or passenger airbag OFF light will turn on if the sensor mat stops working. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion and occupant sensor mat.

### Fuel system

2020054 13 Feb 2020

Issue: Over time, small cracks could develop in the fuel pump outlet. If this happens, there could be a fuel odour or fuel leak under the rear seat area. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump service cover. The fuel filter flanges will be inspected, and replaced if any cracks are found.

### Label

2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

### Accessories

2018661 28 Nov 2018

On certain vehicles equipped with an optional ski bag, the fastening strap for the ski bag may have been sewn with incorrect thread. This could cause the strap seams to tear in the event of crash, which would increase the risk of injury to the passengers. Correction: Dealers will replace the affected ski bags. Note: 72 of the affected ski bags may have been sold as an accessory part through Porsche Dealers.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $27,989[5], $2,135 under the median of $30,124[4].

| | |
|---|---|
| Lowest ask | $23,898 |
| Middle half | $25,744 – $40,035 |
| Median ask | $30,124 |
| This car | $27,989 |

Same configuration · 10 live listings · as of 28 Oct 2026

### OTHER 2018 PORSCHE MACAN LISTINGS [5]

| | |
|---|---|
| Longueuil, QC · 174,265 km | $28,955 |
| Calgary, AB · 41,594 km | $46,467 |
| Thetford Mines, QC · 98,897 km | $32,989 |
| Waterloo, ON · 79,000 km | $24,495 |
| St. Catharines, ON · 78,540 km | $29,995 |
| Calgary, AB · 67,712 km | $42,384 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Leipzig, Germany |
| 28 Nov 2018 | Transport Canada recall 2018661[2]<br>Issued for the model year · Accessories |
| 18 Apr 2019 | Transport Canada recall 2019192[2]<br>Issued for the model year · Label |
| 13 Feb 2020 | Transport Canada recall 2020054[2]<br>Issued for the model year · Fuel system |
| 4 Mar 2021 | Transport Canada recall 2021113[2]<br>Issued for the model year · Airbag |

| | |
|---|---|
| 31 Aug 2022 | Transport Canada recall 2022487[2]<br>Issued for the model year · Lights and instruments |
| 15 Jun 2026 | Listed for sale, Thetford mines, QC[5]<br>Auto Quebec Occasion Thetford Mines · asking $27,989 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $27,989 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.