Register entry, as of 23 November 2026 Listed for sale Record ID daeb4e013721

2017 Audi RS 7 quattro Prestige, quattro Performance Prestige

4.0 L, 8 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WUA	WAAFC	5	H	N	904846
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Sport GmbH	RS 7 · 4.0 L	Computes	2017	Neckarsulm	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	4.0 L, 8 cylinders
Make	Audi	Fuel	Gasoline
Model	RS 7	Drive	AWD
Trim	quattro Prestige, quattro Performance Prestige	Maker	Audi Sport GmbH
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/rs-7/2017

3 recalls listed by Transport Canada for this model year

Engine

2022133 23 Mar 2022

Issue: On certain vehicles, the oil strainer for the turbocharger oil supply could get blocked. If this happens, a turbocharger could fail. This could cause loss of engine power and/or cause the engine to stall. Note: This problem could cause different warning messages to display or the engine oil warning light to turn on. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the oil strainer for the turbocharger oil supply. The dealer will also inspect and document the performance of the boost pressure system and change the engine oil.

Airbag

2018365 6 Jul 2018

On certain vehicles, a problem with the passenger occupant detection system can cause illumination of the airbag warning light and the airbag system may not properly classify the front passenger. In the event of a crash, the airbag system may not function properly, increasing the risk of injury to a front passenger. Correction: Dealers will install a passenger occupant detection system repair kit.

Label

2018075 7 Feb 2018

Certain vehicles may not comply with Canadian Motor Vehicle Safety Regulations. The tire certification label may bear incorrect Gross Vehicle Weight Rating (GVWR) information. The label incorrectly states "520 kg" (1146 lbs) instead of the correct "450 kg" (992 lbs). If an owner were to rely on the incorrect values, it could lead to premature tire failure and vehicle overloading, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will apply a revised certification label with the correct values.

> Listed for the model year, not checked against your VIN. Audi confirms which apply. Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE

No priced market quote for this vehicle yet.

§4 EVENTS

2017	Model year 2017[1] Assembly plant Neckarsulm, Germany
7 Feb 2018	Transport Canada recall 2018075[2] Issued for the model year · Label
6 Jul 2018	Transport Canada recall 2018365[2] Issued for the model year · Airbag
23 Mar 2022	Transport Canada recall 2022133[2] Issued for the model year · Engine
2 Jun 2026	Listed for sale, Burnaby, BC[4] Pioneer Motors Boundary · asking $37,888
22 Nov 2026	Listing last updated[4] asking $37,888

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.