Register entry, as of 28 October 2026 Listed for sale Record ID 8cac6ba9aed7

# 2012 Volkswagen Tiguan

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WVG | CV7AX | 4 | C | W | 540788 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Volkswagen Ag | Tiguan · 2.0 L | Computes | 2012 | Wolfsburg | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2012 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Tiguan | Drive | Not in the decode |
| Trim | Not in the decode | Maker | VOLKSWAGEN AG |
| Body | Sport Utility Vehicle | Plant | Wolfsburg, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2012

**3** recalls listed by Transport Canada for this model year

### Lights and instruments

2020468 6 Oct 2020

Issue: On certain vehicles, the ESC warning light may not remain on if a fault was detected on the previous key cycle. Instead, the warning light does not turn on until the vehicle starts to move. Canadian regulations require that the ESC warning light must turn on when the vehicle is started (under these conditions). Note: This problem can only happen if there is a fault related to the power steering system. The power steering warning light would stay on to advise that there is a fault with the steering system. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to the vehicle software to correct this issue on all new vehicles.

### Seats and restraints

2015344 31 Jul 2015

On certain vehicles, the steering wheel clock spring could become contaminated with long hair or long fibers which may cause a displacement of the internal guide loops. When the guide loops are dragged out of position, they may apply tension to the internal flat cable and cause it to tear. Should the cable tear, the electrical connection to the driver's front airbag may be lost, causing the airbag monitoring indicator light to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will install a cover of a different design to help prevent clock spring contamination caused by hair or other fibers. In instances where the vehicle has an airbag light on (and diagnosis confirms the steering wheel clock spring requires replacement), dealers will install a new steering wheel clock spring.

### Fuel system

2014307 22 Jul 2014

On certain vehicles, deposits may collect on fuel pump connections and reduce fuel pump performance. This could cause the engine to stall, resulting in a loss of motive power and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update vehicle software to increase fuel pump pressure in order to prevent deposits from forming.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $5,995[5], $1,000 under the median of $6,995[4].

| | |
|---|---|
| Lowest ask | $4,522 |
| Middle half | $5,997 – $11,495 |
| Median ask | $6,995 |
| This car | $5,995 |

Same model year · 11 live listings · as of 28 Oct 2026

### OTHER 2012 VOLKSWAGEN TIGUAN LISTINGS [5]

| | |
|---|---|
| Cambridge, ON · 210,629 km | $4,522 |
| Barrie, ON · 154,318 km | $7,995 |
| Barrie, ON · 180,928 km | $6,995 |
| Scarborough, ON · 150,275 km | $6,700 |
| Laval, QC · 158,747 km | $5,999 |
| North Vancouver District, BC · 188,847 km | $5,821 |

## §4 EVENTS

| | |
|---|---|
| 2012 | Model year 2012[1]<br>Assembly plant Wolfsburg, Germany |
| 22 Jul 2014 | Transport Canada recall 2014307[2]<br>Issued for the model year · Fuel system |
| 31 Jul 2015 | Transport Canada recall 2015344[2]<br>Issued for the model year · Seats and restraints |
| 6 Oct 2020 | Transport Canada recall 2020468[2]<br>Issued for the model year · Lights and instruments |
| 25 Oct 2026 | Listed for sale, Vaudreuil-Dorion, QC[5]<br>Prilo Occasion · asking $5,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $5,995 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.