Register entry, as of 29 October 2026 Listed for sale Record ID c72a240e8510

# 2022 Volkswagen Golf R

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
|---|---|---|---|---|---|
| WVW | EB7CD | 9 | N | W | 142102 |
| Volkswagen Ag | Golf R · 2.0 L | Computes | 2022 | Wolfsburg | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Golf R | Drive | Not in the decode |
| Trim | Not in the decode | Maker | VOLKSWAGEN AG |
| Body | Hatchback | Plant | Wolfsburg, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf-r/2022

**6** recalls listed by Transport Canada for this model year

### Visual system

2024365 27 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image to be delayed or not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment software.

### Airbag

2024485 29 May 2024

Issue: On certain vehicles, the owner's manual incorrectly describes the function of the passenger airbag indicator light. Safety Risk: This error does not affect the safety or function of the airbag. Corrective Actions: This is not a recall. The company has made changes to ensure that all new vehicles have owner manuals that correctly describe the function of the passenger airbag indicator light. The company will also instruct dealers to add an insert to correct owner's manuals for all unsold vehicles.

### Visual system

2022630 2 Nov 2022

Issue: On certain vehicles, after shifting into reverse or manually activating the parking function, the rearview camera image may not display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rearview camera.

### Engine
2022533 21 Sep 2022

Issue: On certain vehicles, the radiator may not be attached correctly. As a result, a coolant hose could be damaged by contact with the serpentine belt pulley and create a coolant leak. If this happens, coolant could spill onto the road and cause a red warning light to turn on in the instrument cluster. If you ignore the warning light and continue driving, the engine could overheat. Safety Risk: A coolant leak could create a hazard for other road users. Additionally, an engine that overheats could create the risk of a fire. Corrective Action: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to ensure that the radiator is attached correctly. If it is loose, the coolant hose and serpentine belt will also be checked for damage, and replaced if necessary.

### Visual system
2022402 27 Jul 2022

Issue: On certain vehicles, the touch switch that controls the sunroof may be too sensitive. As a result, the sunroof switch does not pass certain tests under Canadian safety regulations. Safety Risk: A sunroof that closes accidentally could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to contact a dealership to make an appointment to replace the sunroof switch.

### Engine
2022122 16 Mar 2022

Issue: The engine cover may come loose in certain driving conditions. If this happens, the engine cover could contact hot surfaces in the engine compartment and melt. Safety Risk: An engine cover that melts onto a hot surface could create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to remove the engine cover. Volkswagen will send you another notice once a replacement engine cover is available, and will ask you to take your vehicle to a dealer to have it installed.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $40,990[5], $1,995 over the median of $38,995[4].

| | |
|---|---|
| Lowest ask | $33,995 |
| Middle half | $38,000 – $40,990 |
| Median ask | $38,995 |
| This car | $40,990 |

Same model year · 9 live listings · as of 29 Oct 2026

#### OTHER 2022 VOLKSWAGEN GOLF R LISTINGS [5]

| | |
|---|---|
| Oakville, ON · 87,011 km | $40,998 |
| Whitby, ON · 79,892 km | $39,988 |
| Belleville, ON · 99,991 km | $38,000 |
| Amos, QC · 81,736 km | $38,995 |
| Waterloo, ON · 40,727 km | $41,995 |
| Kitchener, ON · 40,727 km | $41,995 |

## §4 EVENTS

2022 Model year 2022[1]
Assembly plant Wolfsburg, Germany

| | |
|---|---|
| 16 Mar 2022 | Transport Canada recall 2022122[2]<br>Issued for the model year · Engine |
| 27 Jul 2022 | Transport Canada recall 2022402[2]<br>Issued for the model year · Visual system |
| 21 Sep 2022 | Transport Canada recall 2022533[2]<br>Issued for the model year · Engine |
| 2 Nov 2022 | Transport Canada recall 2022630[2]<br>Issued for the model year · Visual system |
| 29 May 2024 | Transport Canada recall 2024485[2]<br>Issued for the model year · Airbag |
| 27 Jun 2024 | Transport Canada recall 2024365[2]<br>Issued for the model year · Visual system |
| 29 Oct 2026 | Listed for sale, Port Coquitlam, BC[5]<br>Jim Pattison Hyundai Coquitlam · asking $40,990 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.