

Register entry, as of 28 October 2026

Listed for sale

Record ID 70039d81add7

# 2016 Acura ILX Base/Acura Watch Plus

2.4 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**19U DE2F3 7 G A 803037**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

ILX · 2.4 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

Marysville

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                 |
|------------|-----------------------|--------|---------------------------------|
| Model year | 2016                  | Engine | 2.4 L, 4 cylinders              |
| Make       | Acura                 | Fuel   | Gasoline                        |
| Model      | ILX                   | Drive  | 4x2                             |
| Trim       | Base/Acura Watch Plus | Maker  | AMERICAN HONDA MOTOR CO., INC.  |
| Body       | Sedan                 | Plant  | Marysville, Ohio, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/acura/ilx/2016](https://cardog.app/tools/recalls/acura/ilx/2016)

## 3 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| <b>Brakes</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 2025685 11 Dec 2025 |
| Issue: On certain vehicles, a seal in the brake master cylinder could become damaged. As a result, brake fluid could leak into the reservoir and there could be reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to replace the brake master cylinder.                                                                                                                                                                                                                                                                                                                                                                            |                     |
| <b>Powertrain</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2019272 6 Jun 2019  |
| Issue: On certain cars, the right axle half-shaft could detach. This could cause a loss of power to the drive wheels. Additionally, if the parking brake is not applied, this could allow the car to roll away. Safety Risk: A loss of power to the drive wheels or sudden, unexpected movement of the car could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their car to a dealer to inspect the right driveshaft. If the driveshaft is not fully engaged to the half-shaft, the driveshaft and half-shaft will be replaced.                                                                                                                                                                                                            |                     |
| <b>Airbag</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 2016046 1 Feb 2016  |
| On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844 |                     |



Listed for the model year, not checked against your VIN. Acura confirms which apply.  
Check your VIN with Acura Canada or call a Acura dealer with your VIN.  
[www.acura.ca/en/recalls](http://www.acura.ca/en/recalls)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$14,790<sup>[5]</sup>, \$840 over the median of \$13,950<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$7,999             |
| Middle half | \$11,500 – \$14,988 |
| Median ask  | \$13,950            |
| This car    | \$14,790            |

Same model year · 13 live listings · as of 28 Oct 2026

#### OTHER 2016 ACURA ILX LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Toronto, ON · 146,795 km     | \$13,988 |
| Brossard, QC · 82,662 km     | \$13,995 |
| Hawkesbury, ON · 164,300 km  | \$13,950 |
| Hamilton, ON · 109,250 km    | \$16,999 |
| Markham, ON · 164,155 km     | \$10,998 |
| Scarborough, ON · 183,000 km | \$7,999  |

### §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2016        | Model year 2016 <sup>[1]</sup><br>Assembly plant Marysville, Ohio, United States            |
| 1 Feb 2016  | Transport Canada recall 2016046 <sup>[2]</sup><br>Issued for the model year · Airbag        |
| 6 Jun 2019  | Transport Canada recall 2019272 <sup>[2]</sup><br>Issued for the model year · Powertrain    |
| 11 Dec 2025 | Transport Canada recall 2025685 <sup>[2]</sup><br>Issued for the model year · Brakes        |
| 15 Oct 2026 | Listed for sale, Boucherville, QC <sup>[5]</sup><br>Honda De Boucherville · asking \$14,790 |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$14,790                                      |

### §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.



---

**SOURCES**

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 13 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                               |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

