Register entry, as of 27 October 2026 Listed for sale Record ID 752c24520bc8

2018 Acura ILX Premium Package/Technology Plus Package

2.4 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

19U	DE2F7	5	J	A	801376
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	ILX · 2.4 L	Verified	2018	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.4 L, 4 cylinders
Make	Acura	Fuel	Gasoline
Model	ILX	Drive	4x2
Trim	Premium Package/Technology Plus Package	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/ilx/2018

5 recalls listed by Transport Canada for this model year

Brakes

2025685 11 Dec 2025

Issue: On certain vehicles, a seal in the brake master cylinder could become damaged. As a result, brake fluid could leak into the reservoir and there could be reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to replace the brake master cylinder.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Powertrain

2019272 6 Jun 2019

Issue: On certain cars, the right axle half-shaft could detach. This could cause a loss of power to the drive wheels. Additionally, if the parking brake is not applied, this could allow the car to roll away. Safety Risk: A loss of power to the drive wheels or sudden, unexpected movement of the car could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their car to a dealer to inspect the right driveshaft. If the driveshaft is not fully engaged to the half-shaft, the driveshaft and half-shaft will be replaced.

Fuel system

2019034 25 Jan 2019

Issue: On certain vehicles, the bottom of the fuel tank could be deformed. This could cause the fuel gauge to display the wrong fuel level. This could cause a driver to believe there is fuel when the tank is empty. Safety Risk: The vehicle could unexpectedly run out of fuel and stall, increasing the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection of the fuel tank. All affected fuel tanks will be replaced.

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,880[5], $938 over the median of $18,942[4].

Lowest ask	$9,999
Middle half	$16,925 – $19,557
Median ask	$18,942
This car	$19,880

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2018 ACURA ILX LISTINGS [5]

Toronto, ON · 122,220 km	$18,997
Brampton, ON · 182,724 km	$9,999
Hamilton, ON · 224,000 km	$11,495
Toronto, ON · 128,868 km	$15,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant Marysville, Ohio, United States
25 Jan 2019	Transport Canada recall 2019034[2] Issued for the model year · Fuel system
6 Jun 2019	Transport Canada recall 2019272[2] Issued for the model year · Powertrain
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system

6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
11 Dec 2025	Transport Canada recall 2025685[2] Issued for the model year · Brakes
14 Oct 2026	Listed for sale, Vancouver, BC[5] Southside Nissan · asking $19,880
25 Oct 2026	Listing last updated[5] asking $19,880

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.