Register entry, as of 28 October 2026 Listed for sale Record ID 89f19fbc8f16

# 2015 Acura TLX ADVANCE V6

3.5 L, 6 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 19U | UB2F7 | 1 | F | A | 800094 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Acura · AMERICAN HONDA… | TLX · 3.5 L | Verified | 2015 | Marysville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 3.5 L, 6 cylinders |
| Make | Acura | Fuel | Gasoline |
| Model | TLX | Drive | FWD |
| Trim | ADVANCE V6 | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sedan | Plant | Marysville, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/tlx/2015

**4** recalls listed by Transport Canada for this model year

### Engine — 2023603 — 8 Nov 2023

Issue: On certain vehicles equipped with a V6 engine, the connecting rod bearings could wear prematurely and become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Safety Risk: An engine failure could cause a sudden loss of power and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the engine. If damage is found, the dealer will replace the necessary parts.

### Powertrain — 2016428 — 2 Sep 2016

On certain vehicles, the transmission wire harness connections may have been improperly crimped. This could cause an unexpected shift to neutral which could result in a loss of motive power, which in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash. Correction: Dealers will update vehicle software to eliminate the potential for an unexpected loss of motive power due to this issue.

### Powertrain — 2014538 — 28 Nov 2014

On certain vehicles equipped with 9-speed automatic transmissions, the PARK pawl may not properly engage. If the parking pawl fails to engage and the driver does not use the electric parking brake, the vehicle may roll away after the brake pedal is released, which could result in a crash causing injury and/or damage to property. Correction: Dealers will inspect the transmission and repair if necessary.

### Label

2014431 30 Sep 2014

Certain vehicles may not comply with Canadian Motor Vehicle Safety Regulations. The compliance label may bear incorrect Gross Vehicle Weight Rating (GVWR) and Gross Axle Weight Rating (GAWR) information. This could result in vehicle overloading, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will apply a revised label.

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $12,999[5], $1,000 under the median of $13,999[4].




| | |
|---|---|
| Lowest ask | $8,495 |
| Middle half | $11,995 – $16,999 |
| Median ask | $13,999 |
| This car | $12,999 |

Same model year · 29 live listings · as of 28 Oct 2026

### OTHER 2015 ACURA TLX LISTINGS [5]

| | |
|---|---|
| Sherwood Park, AB · 203,643 km | $12,507 |
| Edmonton, AB · 146,717 km | $17,950 |
| Barrie, ON · 217,605 km | $8,495 |
| Laval, QC · 191,000 km | $8,799 |
| Mississauga, ON · 170,016 km | $10,800 |
| Quebec, QC · 116,917 km | $15,987 |

## §4 EVENTS

| | |
|---|---|
| 2015 | Model year 2015[1]<br>Assembly plant Marysville, Ohio, United States |
| 30 Sep 2014 | Transport Canada recall 2014431[2]<br>Issued for the model year · Label |
| 28 Nov 2014 | Transport Canada recall 2014538[2]<br>Issued for the model year · Powertrain |
| 2 Sep 2016 | Transport Canada recall 2016428[2]<br>Issued for the model year · Powertrain |
| 8 Nov 2023 | Transport Canada recall 2023603[2]<br>Issued for the model year · Engine |
| 27 Nov 2025 | Listed for sale, Toronto, ON[5]<br>11 MOTORS · asking $12,999 |

| | |
|---|---|
| 27 Oct 2026 | Listing last updated[5]<br>asking $12,999 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 29 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.