Register entry, as of 28 October 2026 Listed for sale Record ID 54513dbfc22f

2021 Acura TLX Platinum Elite

2.0 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

19U	UB6F9	2	M	A	800367
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	TLX · 2.0 L	Verified	2021	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Acura	Fuel	Gasoline
Model	TLX	Drive	4WD
Trim	Platinum Elite	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/tlx/2021

4 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Brakes

2025318 12 Jun 2025

Issue: On certain vehicles, the brake pedal assembly may not have been manufactured properly. As a result, the brake pedal could move and cause you not to be able to apply the brakes properly, or to apply the brakes unexpectedly. This could also cause the brake lights to turn on without pressing the brake pedal. Safety Risk: Reduced braking and/or braking unexpectedly could increase the risk of a crash. Additionally, brake lights that turn on without the brake pedal being pressed could cause others not to recognize when the vehicle is braking or not braking and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the brake pedal assembly.

Fuel system

2025029 23 Jan 2025

Issue: On certain vehicles, a software problem in the fuel injection electronic control unit could cause the engine to stall while driving. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the fuel injection electronic control unit software.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $33,880[5], $132 over the median of $33,748[4].

Lowest ask	$26,495
Middle half	$31,989 – $33,994
Median ask	$33,748
This car	$33,880

Same model year · 14 live listings · as of 28 Oct 2026

OTHER 2021 ACURA TLX LISTINGS [5]

Huntsville, ON · 88,289 km	$31,986
Dollard-Des Ormeaux, QC · 60,496 km	$30,995
Pickering, ON · 27,967 km	$35,188
Calgary, AB · 131,317 km	$33,697
Edmonton, AB · 74,151 km	$55,888
Laval, QC · 54,702 km	$33,990

§4 EVENTS

2021	Model year 2021[1] Assembly plant Marysville, Ohio, United States
1 Feb 2024	Transport Canada recall 2024059[2] Issued for the model year · Airbag
23 Jan 2025	Transport Canada recall 2025029[2] Issued for the model year · Fuel system
12 Jun 2025	Transport Canada recall 2025318[2] Issued for the model year · Brakes
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints

25 Oct 2026	Listed for sale, Mississauga, ON[5] Eknoor Auto Sales · asking $33,880
28 Oct 2026	Listing last updated[5] asking $33,880

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 14 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.