Register entry, as of 29 October 2026 Listed for sale Record ID db379cc84ac3

# 2012 Honda Civic LX

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 19X | FB2F5 | 6 | C | E | 105916 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Civic · 1.8 L | Verified | 2012 | Greensburg | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2012 | Engine | 1.8 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Civic | Drive | Not in the decode |
| Trim | LX | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sedan | Plant | Greensburg, Indiana, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2012

**4** recalls listed by Transport Canada for this model year

### Powertrain

2020610 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

### Powertrain

2012174 1 Jun 2012

On certain vehicles equipped with automatic transmissions, the driver's side driveshaft could separate from the CV joint due to an improperly seated snap ring. This could result in a loss of vehicle propulsion, or allow the vehicle to roll away despite being set in the PARK position. Loss of vehicle propulsion, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Also, the vehicle rolling away could result in property damage and/or personal injury. Correction: Dealers will inspect the driveshaft and replace if necessary.

### Airbag

2012031 31 Jan 2012

On certain vehicles, the side curtain airbag inflators may have been incorrectly manufactured and, as a result, one or both airbags may not deploy as intended. Failure of a side curtain airbag to deploy during a crash (where deployment is warranted), could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect and, if necessary, replace one or both side curtain airbag assemblies.

### Fuel system

2011200 17 May 2011

On certain vehicles, the fuel supply line may have been manufactured incorrectly, which could allow a fuel leak to develop. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel supply line.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $5,995[5], $2,502 under the median of $8,497[4].




| | |
|---|---|
| Lowest ask | $2,995 |
| Middle half | $6,371 – $9,962 |
| Median ask | $8,497 |
| This car | $5,995 |

Same model year · 36 live listings · as of 29 Oct 2026

OTHER 2012 HONDA CIVIC LISTINGS [5]

| | |
|---|---|
| Montréal, QC · 252,220 km | $4,999 |
| Vancouver, BC · 0 km | $9,999 |
| Winnipeg, MB · 207,747 km | $8,499 |
| Matane, QC · 117,260 km | $8,950 |
| Hamilton, ON · 297,038 km | $2,999 |
| Laval, QC · 169,000 km | $4,999 |

## §4 EVENTS

| | |
|---|---|
| 2012 | Model year 2012[1]<br>Assembly plant Greensburg, Indiana, United States |
| 17 May 2011 | Transport Canada recall 2011200[2]<br>Issued for the model year · Fuel system |
| 31 Jan 2012 | Transport Canada recall 2012031[2]<br>Issued for the model year · Airbag |
| 1 Jun 2012 | Transport Canada recall 2012174[2]<br>Issued for the model year · Powertrain |
| 10 Dec 2020 | Transport Canada recall 2020610[2]<br>Issued for the model year · Powertrain |
| 20 Oct 2026 | Listed for sale, Toronto, ON[5]<br>SCARBORO E AUTO LIMITED · asking $5,995 |

| | |
|---|---|
| 28 Oct 2026 | Listing last updated[5]<br>asking $5,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 36 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.