

Register entry, as of 27 October 2026

Listed for sale

Record ID ef9540394751

# 2015 Chrysler 200 Limited

2.4 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1C3 CCCAB 6 F N 625850**

WMI 1-3

Chrysler · FCA US LLC

DESCRIPTOR 4-8

200 · 2.4 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Sterling Heights

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |          |        |                                           |
|------------|----------|--------|-------------------------------------------|
| Model year | 2015     | Engine | 2.4 L, 4 cylinders                        |
| Make       | Chrysler | Fuel   | Gasoline                                  |
| Model      | 200      | Drive  | FWD                                       |
| Trim       | Limited  | Maker  | FCA US LLC                                |
| Body       | Sedan    | Plant  | Sterling Heights, Michigan, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/chrysler/200/2015](https://cardog.app/tools/recalls/chrysler/200/2015)

## 8 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| Label                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 2024548 15 Aug 2024 |
| Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.                                                                          |                     |
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 2018269 17 May 2018 |
| On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired. |                     |
| Powertrain                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 2016361 13 Jul 2016 |
| On certain vehicles equipped with an automatic transmission, the transmission wire harness may have improper crimps. This could cause an unexpected shift to neutral which could result in a loss of motive power, which in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash. Correction: Dealers will update the software of the Transmission Control Module (TCM), and replace the transaxle wire harness as necessary.                                                                                             |                     |



**Airbag**

2016098 29 Feb 2016

Certain vehicles may have had the front passenger seat occupant classification module or seat cushion foam replaced during regular servicing with a portion of a service kit. These components should have been installed together as a calibrated set. If a vehicle only had a portion of the service kit installed, occupant classification system function could be affected, which could potentially increase the risk of an improper passenger airbag deployment in a crash (when warranted), increasing the risk of injury to the occupant. Correction: In vehicles where a portion of a service kit was installed, dealers will install a full seat service kit.

**Engine**

2015327 22 Jul 2015

On certain vehicles equipped with either a 2.4L engine or a 3.6L engine, the Power Distribution Center (PDC) 12-wire connector contains terminals that may have been damaged during the manufacturing process. These damaged PDC connector terminal(s) could cause intermittent electrical connection(s) which could result in the engine stalling without warning and/or the transaxle defaulting to "Neutral." If this were to occur under certain driving conditions, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will either replace the C4 connector using a 12 wire splice kit (3.6L engine) or replace the transmission wiring harness (2.4L engine).

**Powertrain**

2015069 17 Feb 2015

On certain vehicles equipped with 9-speed automatic transmissions, the PARK pawl may not properly engage. If the parking pawl fails to engage and the driver does not use the parking brake, the vehicle may roll away after the brake pedal is released, which could result in a crash causing injury and/or damage to property. Correction: Dealers will inspect the transmission and repair if necessary.

2 more on the model-year record, [cardog.app/tools/recalls/chrysler/200/2015](http://cardog.app/tools/recalls/chrysler/200/2015)

Listed for the model year, not checked against your VIN. Chrysler confirms which apply.

Check your VIN with Mopar Canada or call a Chrysler dealer with your VIN.

[www.mopar.com/en-ca/my-vehicle/recalls/search.html](http://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$11,980<sup>[5]</sup>, \$2,496 over the median of \$9,484<sup>[4]</sup>.



|             |                    |
|-------------|--------------------|
| Lowest ask  | \$4,909            |
| Middle half | \$8,498 – \$11,238 |
| Median ask  | \$9,484            |
| This car    | \$11,980           |

Same model year · 28 live listings · as of 27 Oct 2026

**OTHER 2015 CHRYSLER 200 LISTINGS** <sup>[5]</sup>

|                                        |          |
|----------------------------------------|----------|
| Courtenay, BC · 104,871 km             | \$12,998 |
| Parksville, BC · 104,871 km            | \$12,998 |
| Prince George, BC · 207,151 km         | \$4,909  |
| Steinbach, MB · 92,634 km              | \$12,995 |
| Châteauguay, QC · 109,928 km           | \$11,995 |
| Saint-Lin-Laurentides, QC · 125,836 km | \$9,495  |



## §4 EVENTS

|             |                                                                                              |
|-------------|----------------------------------------------------------------------------------------------|
| 2015        | Model year 2015 <sup>[1]</sup><br>Assembly plant Sterling Heights, Michigan, United States   |
| 3 Jul 2014  | Transport Canada recall 2014276 <sup>[2]</sup><br>Issued for the model year · Suspension     |
| 6 Aug 2014  | Transport Canada recall 2014336 <sup>[2]</sup><br>Issued for the model year · Electrical     |
| 17 Feb 2015 | Transport Canada recall 2015069 <sup>[2]</sup><br>Issued for the model year · Powertrain     |
| 22 Jul 2015 | Transport Canada recall 2015327 <sup>[2]</sup><br>Issued for the model year · Engine         |
| 29 Feb 2016 | Transport Canada recall 2016098 <sup>[2]</sup><br>Issued for the model year · Airbag         |
| 13 Jul 2016 | Transport Canada recall 2016361 <sup>[2]</sup><br>Issued for the model year · Powertrain     |
| 17 May 2018 | Transport Canada recall 2018269 <sup>[2]</sup><br>Issued for the model year · Engine         |
| 15 Aug 2024 | Transport Canada recall 2024548 <sup>[2]</sup><br>Issued for the model year · Label          |
| 16 Sep 2025 | Listed for sale, New Westminster, BC <sup>[5]</sup><br>Alliance Motor Cars · asking \$11,980 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$11,980                                       |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 28 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

